

RESERVE STUDY FOR TEMPE VILLAGES HOMEOWNERS ASSOCIATION, INC



Management By: Vision Community Management 16625 S. Desert Foothills Pkwy Phoenix, AZ 85044

> Prepared By: FDReserve Studies, LLC Goodyear, AZ 85338 8/31/2016



EXECUTIVE SUMMARY

TEMPE VILLAGES HOMEOWNERS ASSOCIATION, INC

8/31/2016

| Starting Reserve Balance 1/1/2016 | \$107,635 |
|---|-----------|
| Projected Fully Funded Reserve Balance 1/1/2016 | \$581,617 |
| Percent Fully Funded | 18% |
| Annual Reserve Contribution | \$26,000 |

- 1. Reserve fund is grossly underfunded at the current assessment reflected in current assessment funding model.
- 2. An alternate funding plan has been prepared for your consideration. This is a way to show you how to get the reserve fund in a healthy state.

TABLE OF CONTENTS Tempe Villages HOA

PART I • INFORMATION ABOUT YOUR RESERVE STUDY

| Important Information | 1- |
|--|------|
| Introduction | |
| Funding Options | |
| Types of Reserve Studies | |
| Developing a Component List | |
| Operational Expenses | |
| Reserve Expenses | 1 |
| Funding Methods | |
| Funding Strategies | |
| Distribution of Reserves | |
| User's Guide to Your Reserve Study | |
| Definitions | 1-9 |
| Your Reserve Study is a Multi-Purpose Tool | 1-13 |

PART II • RESERVE STUDY

| Current Assessment Funding Model Summary | 2-1 |
|--|------|
| Current Assessment Funding Model Projection | 2-2 |
| Current Assessment Funding Model VS Fully Funded | 2-3 |
| Alternate Funding Model 1 Summary | 2-4 |
| Alternate Funding Model 1 Projection | 2-5 |
| Annual Expenditure Detail | 2-6 |
| Detail Report by Category | 2-15 |
| Category Detail Index | 2-47 |
| Spread Sheet | 2-49 |

Important Information

This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by representatives of the association, its contractors, assorted vendors, specialist and independent contractors, the Community Association Institute, and various construction pricing and scheduling manuals including, but not limited to: Marshall & Swift Valuation Service, RS Means Facilities Maintenance & Repair Cost Data, RS Means Repair & Remodeling Cost Data, National Construction Estimator, National Repair & Remodel Estimator, Dodge Cost Manual and McGraw-Hill Professional. Additionally, costs are obtained from numerous vendor catalogues, actual quotations or historical costs, and our own experience in the field of property management and reserve study preparation.

It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications. In some cases, estimates may have been used on assets, which have an indeterminable but potential liability to the association. The decision for the inclusion of these as well as all assets considered is left to the client.

Part I

Document

This reserve analysis study is provided as an aid for planning purposes and not as an accounting tool. Since it deals with events yet to take place, there is no assurance that the results enumerated within it will, in fact, occur as described.

Preparing the annual budget and overseeing the association's finances are perhaps the most important responsibilities of board members. The annual operating and reserve budgets reflect the planning and goals of the association and set the level and quality of service for all of the association's activities.

Funding Options

When a major repair or replacement is required in a community, an association has essentially four options available to address the expenditure:

The first, and only logical means that the Board of Directors has to ensure its ability to maintain the assets for which it is obligated, is by **assessing an adequate level of reserves** as part of the regular membership assessment, thereby distributing the cost of the replacements uniformly over the entire membership. The community is not only comprised of present members, but also future members. Any decision by the Board of Directors to adopt a calculation method or funding plan which would disproportionately burden future members in order to make up for past reserve deficits, would be a breach of its fiduciary responsibility to those future members. Unlike individuals determining their own course of action, the board is responsible to the "community" as a whole.

Whereas, if the association was setting aside reserves for this purpose, using the vehicle of the regularly assessed membership dues, it would have had the full term of the life of the roof, for example, to accumulate the necessary moneys. Additionally, those contributions would have been evenly distributed over the entire membership and would have earned interest as part of that contribution.

The second option is for the association to **acquire a loan** from a lending institution in order to effect the required repairs. In many cases, banks will lend to an association using "future homeowner assessments" as collateral for the loan. With this method, the <u>current</u> board is pledging the <u>future</u> assets of an association. They are also incurring the additional expense of interest fees along with the original principal amount. In the case of a \$150,000 roofing replacement, the association may be required to pay back the loan over a three to five year period, with interest.

The third option, too often used, is simply to **defer the required repair or replacement**. This option, which is not recommended, can create an environment of declining property values due to expanding lists of deferred maintenance items and the association's financial inability to keep pace with the normal aging process of the common area components. This, in turn, can have a seriously negative impact on sellers in the association by making it difficult, or even impossible, for potential buyers to obtain financing from lenders. Increasingly, lending institutions are requesting copies of the association's most recent reserve study before granting loans, either for the association itself, a prospective purchaser, or for an individual within such an association.

The fourth option is to pass a "**special assessment**" to the membership in an amount required to cover the expenditure. When a special assessment is passed, the association has the authority and responsibility to collect the assessments, even by means of foreclosure, if necessary. However, an association considering a special assessment cannot guarantee that an assessment, when needed, will be passed. Consequently, the association cannot guarantee its ability to perform the required repairs or replacements to those major components for which it is obligated when the need arises. Additionally, while relatively new communities require very little in the way of major "reserve" expenditures, associations reaching 12 to 15 years of age and older, find many components reaching the end of their effective useful lives. These required expenditures, all accruing at the same time, could be devastating to an association's overall budget.

Types of Reserve Studies

Most reserve studies fit into one of three categories:

Full Reserve Study;

Update with site inspection; and

Update without site inspection.

In a **Full Reserve Study**, the reserve provider conducts a component inventory, a condition assessment (based upon on-site visual observations), and life and valuation estimates to determine both a "fund status" and "funding plan".

In an **Update** <u>with</u> site inspection, the reserve provider conducts a component inventory (verification only, not quantification unless new components have been added to the inventory), a condition assessment (based upon on-site visual observations), and life and valuation estimates to determine both the "fund status and "funding plan."

In an **Update** <u>without</u> site inspection, the reserve provider conducts life and valuation estimates to determine the "fund status" and "funding plan."

The Reserve Study: A Physical and a Financial Analysis

There are two components of a reserve study: a physical analysis and a financial analysis.

Physical Analysis

During the physical analysis, a reserve study provider evaluates information regarding the physical status and repair/replacement cost of the association's major common area components. To do so, the provider conducts a component inventory, a condition assessment, and life and valuation estimates.

Developing a Component List

The budget process begins with full inventory of all the major components for which the association is responsible. The determination of whether an expense should be labeled as operational, reserve, or excluded altogether is sometimes subjective. Since this labeling may have a major impact on the financial plans of the association, subjective determinations should be minimized. We suggest the following considerations when labeling an expense.

Operational Expenses

Occur at least annually, no matter how large the expense, and can be budgeted for effectively each year. They are characterized as being reasonably predictable, both in terms of frequency and cost. Operational expenses include all minor expenses, which would not otherwise adversely affect an operational budget from one year to the next. Examples of *operational expenses* include:

| Utilities: | Bank Service Charges | Accounting |
|-----------------|--------------------------|--------------------------|
| Electricity | Dues & Publications | Reserve Study |
| Gas | Licenses, Permits & Fees | Repair Expenses: |
| Water | Insurance(s) | Tile Roof Repairs |
| Telephone | Services: | Equipment Repairs |
| Cable TV | Landscaping | Minor Concrete Repairs |
| Administrative: | Pool Maintenance | Operating Contingency |
| Supplies | Street Sweeping | |

Reserve Expenses

These are major expenses that occur other than annually, and which must be budgeted for in advance in order to ensure the availability of the necessary funds in time for their use. Reserve expenses are reasonably predictable both in terms of frequency and cost. However, they may include significant assets that have an indeterminable but potential liability that may be demonstrated as a likely occurrence. They are expenses that, when incurred, would have a significant effect on the smooth operation of the budgetary process from one year to the next, if they were not reserved for in advance. Examples of reserve expenses include:

| Roof Replacements | Park/Play Equipment |
|-----------------------|----------------------------|
| Painting | Pool/Spa Re-plastering |
| Deck Resurfacing | Pool Equipment Replacement |
| Fencing Replacement | Pool Furniture Replacement |
| Asphalt Seal Coating | Tennis Court Resurfacing |
| Asphalt Repairs | Lighting Replacement |
| Asphalt Overlays | Insurance(s) |
| Equipment Replacement | Reserve Study |
| Interior Furnishings | |

Budgeting is Normally Excluded for:

Repairs or replacements of assets which are deemed to have an estimated useful life equal to or exceeding the estimated useful life of the facility or community itself, or exceeding the legal life of the community as defined in an association's governing documents. Examples include the complete replacement of elevators, tile roofs, wiring and plumbing. Also excluded are insignificant expenses that may be covered either by an operating or reserve contingency, or otherwise in a general maintenance fund. Expenses that are necessitated by acts of nature, accidents or other occurrences that are more properly insured for, rather than reserved for, are also excluded.

Financial Analysis

The financial analysis assesses the association's reserve balance or "fund status" (measured in cash or as percent fully funded) to determine a recommendation for the appropriate reserve contribution rate in the future, known as the "funding plan".

Preparing the Reserve Study

Once the reserve assets have been identified and quantified, their respective replacement costs, useful lives and remaining lives must be assigned so that a funding schedule can be constructed. Replacement costs and useful lives can be found in published manuals such as construction estimators, appraisal handbooks, and valuation guides. Remaining lives are calculated from the useful lives and ages of assets and adjusted according to conditions such as design, manufactured quality, usage, exposure to the elements and maintenance history.

By following the recommendations of an effective reserve study, the association should avoid any major shortfalls. However, to remain accurate, the report should be updated on an annual basis to reflect such changes as shifts in economic parameters, additions of phases or assets, or expenditures of reserve funds. The association can assist in simplifying the reserve analysis update process by keeping accurate records of these changes throughout the year.

Funding Methods

From the simplest to the most complex, reserve analysis providers use many different computational processes to calculate reserve requirements. However, there are two basic processes identified as industry standards: the cash flow method and the component method.

The cash flow method develops a reserve-funding plan where contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the actual anticipated schedule of reserve expenses until the desired funding goal is achieved. This method sets up a "window" in which all future anticipated replacement costs are computed, based upon the individual lives of the components under consideration. The Threshold and the Current Assessment funding models are based upon the cash flow method.

The component method develops a reserve-funding plan where the total contribution is based upon the sum of contributions for individual components. The component method is the more conservative of the two funding options, and assures that the association will achieve and maintain an ideal level of reserve over time. This method also allows for computations on individual components in the analysis. The Component Funding model is based upon the component methodology.

Funding Strategies

Once an association has established its funding goals, the association can select an appropriate funding plan. There are four basic strategies from which most associations select. It is recommended that associations consult professionals to determine the best strategy or combination of plans that best suit the association's need. Additionally, associations should consult with their financial advisor to determine the tax implications of selecting a particular plan. Further, consultation with the American Institute of Certified Public Accountants (AICPA) for their reporting requirements is advisable. The four funding plans and descriptions of each are detailed below. Associations will have to update their reserve studies more or less frequently depending on the funding strategy they select.

Full Funding---Given that the basis of funding for reserves is to distribute the costs of the replacements over the lives of the components in question, it follows that the ideal level of reserves would be proportionately related to those lives and costs. If an association has a component with an expected estimated useful life of ten years, it would set aside approximately one-tenth of the replacement cost each year. At the end of three years, one would expect three-tenths of the replacement cost to have accumulated, and if so, that component would be "fully-funded." This model is important in that it is a measure of the adequacy of an association's reserves at any one point of time, and is independent of any particular method which may have been used for past funding or may be under consideration for future funding. This formula represents a snapshot in time and is based upon current replacement cost, independent of future inflationary or investment factors:

Fully Funded Reserves = Age divided by Useful Life the results multiplied by Current Replacement Cost

When an association's total accumulated reserves for all components meet this criterion, its reserves are considered "fully-funded."

The **Threshold Funding Model (Minimum Funding)**. The goal of this funding method is to keep the reserve cash balance above zero. This means that while each individual component may not be fully funded, the reserve balance overall does not drop below zero during the projected period. An association using this funding method must understand that even a minor reduction in a component's remaining useful life can result in a deficit in the reserve cash balance.

The **Threshold Funding Model.** This method is based upon the cash flow funding concept. The minimum reserve cash balance in threshold funding, however, is set at a predetermined dollar amount (other than \$0).

The **Current Assessment Funding Model**. This method is also based upon the cash flow funding concept. The initial reserve assessment is set at the association's current fiscal year funding level and a 30-year projection is calculated to illustrate the adequacy of the current funding over time.

The **Component Funding Model**. This is a straight-line funding model. It distributes the cash reserves to individual reserve components and then calculates what the reserve assessment and interest contribution (minus taxes) should be, again by each reserve component. The current annual assessment is then determined by summing all the individual component assessments, hence the name "Component Funding Model". This is the most conservative funding model. It leads to or maintains the fully funded reserve position. The following details this calculation process.

Component Funding Model Distribution of Accumulated Reserves

The "Distribution of Accumulated Reserves Report" is a "Component Funding Model" calculation. This distribution **<u>does not</u>** apply to the cash flow funding models.

When calculating reserves based upon the component methodology, a beginning reserve balance must be

allocated for each of the individual components considered in the analysis, before the individual calculations can be completed. When this distribution is not available, or of sufficient detail, the following method is suggested for allocating reserves:

The first step the program performs in this process is subtracting, from the total accumulated reserves, any amounts for assets that have predetermined (fixed) reserve balances. The user can "fix" the accumulated reserve balance within the program on the individual asset's detail page. If, by error, these amounts total more than the amount of funds available, then the remaining assets are adjusted accordingly. A provision for a contingency reserve is then deducted by the determined percentage used, and if there are sufficient remaining funds available.

The second step is to identify the ideal level of reserves for each asset. As indicated in the prior section, this is accomplished by evaluating the component's age proportionate to its estimated useful life and current replacement cost. Again, the equation used is as follows:

Fully Funded Reserves = (Age/Useful Life) x Current Replacement Cost

The software program performs the above calculations to the actual month the component was placedin-service. The program projects that the accumulation of necessary reserves for repairs or replacements will be available on the first day of the fiscal year in which they are scheduled to occur.

The next step the program performs is to arrange all of the assets used in the study in ascending order by remaining life, and alphabetically within each grouping of remaining life items. These assets are then assigned their respective ideal level of reserves until the amount of funds available is depleted, or until all assets are appropriately funded. If any assets are assigned a zero remaining life (scheduled for replacement in the current fiscal year), then the amount assigned equals the current replacement cost and funding begins for the next cycle of replacement. If there are insufficient funds available to accomplish this, then the software automatically adjusts the zero remaining life items to one year, and that asset assumes its new grouping position alphabetically in the final printed report.

If, at the completion of this task, there are additional moneys that have not been distributed, the remaining reserves are then assigned, in ascending order, to a level equal to, but not exceeding, the current replacement cost for each component. If there are sufficient moneys available to fund all assets at their current replacement cost levels, then any excess funds are designated as such and are not factored into any of the report computations. If, at the end of this assignment process there are designated excess funds, they can be used to offset the monthly contribution requirements recommended, or used in any other manner the client may desire.

Assigning the reserves in this manner defers the make-up period for any under-funding over the longest remaining life of all assets under consideration, thereby minimizing the impact of any deficiency. For example, if the report indicates an under funding of \$50,000, this under-funding will be assigned to components with the longest remaining lives in order to give more time to "replenish" the account. If the \$50,000 under-funding were to be assigned to short remaining life items, the impact would be felt immediately.

If the reserves are under-funded, the monthly contribution requirements, as outlined in this report, can be expected to be higher than normal. In future years, as individual assets are replaced, the funding requirements will return to their normal levels. In the case of a large deficiency, a special assessment may be considered. The program can easily generate revised reports outlining how the monthly contributions would be affected by such an adjustment, or by any other changes that may be under consideration.

Funding Reserves

Three assessment and contribution figures are provided in the report, the "Monthly Reserve Assessment

Required", the "Average Net Monthly Interest Earned" contribution and the "Total Monthly Allocation to Reserves." The association should allocate the "Monthly Reserve Assessment Required" amount to reserves each month when the interest earned on the reserves is left in the reserve accounts as part of the contribution. Any interest earned on reserve deposits, must be left in reserves and only amounts set aside for taxes should be removed.

The second alternative is to allocate the "Total Monthly Allocation" to reserves (this is the member assessment plus the anticipated interest earned for the fiscal year). This method assumes that all interest earned will be assigned directly as operating income. This allocation takes into consideration the anticipated interest earned on accumulated reserves regardless of whether or not it is actually earned. When taxes are paid, the amount due will be taken directly from the association's operating accounts as the reserve accounts are allocated only those moneys net of taxes.

Users' Guide to your Reserve Analysis Study

Part II of your report contains the reserve analysis study for your association. There are seven types of reports in the study as described below.

Report Summaries

The Report Summary for all funding models lists all of the parameters that were used in calculating the report as well as the summary of your reserve analysis study.

Index Reports

The **Distribution of Accumulated Reserves** report lists all assets in remaining life order. It also identifies the ideal level of reserves that should have accumulated for the association as well as the actual reserves available. This information is valid only for the "Component Funding Model" calculation.

The **Component Listing/Summary** lists all assets by category (i.e. roofing, painting, lighting, etc.) together with their remaining life, current cost, monthly reserve contribution, and net monthly allocation.

Detail Reports

The Detail Report itemizes each asset and lists all measurements, current and future costs, and calculations for that asset. Provisions for percentage replacements, salvage values, and one-time replacements can also be utilized. These reports can be sorted by category or group.

The numerical listings for each asset are enhanced by extensive narrative detailing factors such as design, manufactured quality, usage, exposure to elements and maintenance history.

The Detail Index is an alphabetical listing of all assets, together with the page number of the asset's detail report, the projected replacement year, and the asset number.

Projections

Thirty-year projections add to the usefulness of your reserve analysis study.

Definitions

Report I.D.

Includes the Report Date (example: November 15, 1992), Account Number (example: 9773), and Version (example: 1.0). Please use this information (displayed on the summary page) when referencing your report.

Budget Year Beginning/Ending

The budgetary year for which the report is prepared. For associations with fiscal years ending December 31^{st} , the monthly contribution figures indicated are for the 12-month period beginning 1/1/20xx and ending 12/31/20xx.

Number of Units and/or Phases

If applicable, the number of units and/or phases included in this version of the report.

Inflation

This figure is used to approximate the future cost to repair or replace each component in the report. The current cost for each component is compounded on an annual basis by the number of remaining years to replacement, and the total is used in calculating the monthly reserve contribution that will be necessary to accumulate the required funds in time for replacement.

Annual Assessment Increase

This represents the percentage rate at which the association will increase its assessment to reserves at the end of each year. For example, in order to accumulate \$10,000 in 10 years, you could set aside \$1,000 per year. As an alternative, you could set aside \$795 the first year and increase that amount by 5% each year until the year of replacement. In either case you arrive at the same amount. The idea is that you start setting aside a lower amount and increase that number each year in accordance with the planned percentage. Ideally this figure should be equal to the rate of inflation. It can, however, be used to aide those associations that have not set aside appropriate reserves in the past, by making the initial year's allocation less formidable.

Investment Yield Before Taxes

The average interest rate anticipated by the association based upon its current investment practices.

Taxes on Interest Yield

The estimated percentage of interest income that will be set aside to pay income taxes on the interest earned.

Projected Reserve Balance

The anticipated reserve balance on the first day of the fiscal year for which this report has been prepared. This is based upon information provided and not audited.

Percent Fully Funded

The ratio, at the beginning of the fiscal year, of the actual (or projected) reserve balance to the calculated fully funded balance, expressed as a percentage.

Phase Increment Detail and/or Age

Comments regarding aging of the components on the basis of construction date or date of acceptance by the association.

Monthly Assessment

The assessment to reserves required by the association each month.

Interest Contribution (After Taxes)

The interest that should be earned on the reserves, net of taxes, based upon their beginning reserve balance and monthly contributions for one year. This figure is averaged for budgeting purposes.

Total Monthly Allocation

The sum of the monthly assessment and interest contribution figures.

Group and Category

The report may be prepared and sorted either by group (location, building, phase, etc.) or by category (roofing, painting, etc.). The standard report printing format is by category.

Percentage of Replacement or Repairs

In some cases, an asset may not be replaced in its entirety or the cost may be shared with a second party. Examples are budgeting for a percentage of replacement of streets over a period of time, or sharing the expense to replace a common wall with a neighboring party.

Placed-In-Service Date

The month and year that the asset was placed-in-service. This may be the construction date, the first escrow closure date in a given phase, or the date of the last servicing or replacement.

Estimated Useful Life

The estimated useful life of an asset based upon industry standards, manufacturer specifications, visual inspection, location, usage, association standards and prior history. All of these factors are taken into consideration when tailoring the estimated useful life to the particular asset. For example, the carpeting in a hallway or elevator (a heavy traffic area) will not have the same life as the identical carpeting in a seldom-used meeting room or office.

Adjustment to Useful Life

Once the useful life is determined, it may be adjusted, up or down, by this separate figure for the current cycle of replacement. This will allow for a current period adjustment without affecting the estimated replacement cycles for future replacements.

Estimated Remaining Life

This calculation is completed internally based upon the report's fiscal year date and the date the asset

was placed-in-service.

Replacement Year

The year that the asset is scheduled to be replaced. The appropriate funds will be available by the first day of the fiscal year for which replacement is anticipated.

Annual Fixed Reserves

An optional figure which, if used, will override the normal process of allocating reserves to each asset.

Fixed Assessment

An optional figure which, if used, will override all calculations and set the assessment at this amount. This assessment can be set for monthly, quarterly or annually as necessary.

Salvage Value

The salvage value of the asset at the time of replacement, if applicable.

One-Time Replacement

Notation if the asset is to be replaced on a one-time basis.

Current Replacement Cost

The estimated replacement cost effective at the beginning of the fiscal year for which the report is being prepared

Future Replacement Cost

The estimated cost to repair or replace the asset at the end of its estimated useful life based upon the current replacement cost and inflation.

Component Inventory

The task of selecting and qualifying reserve components. This task can be accomplished through on-site visual, review of association design and organizational documents, a review of established association precedents, and discussion with appropriate association representative(s).

A Multi-Purpose Tool

Your Report is an important part of your association's budgetary process. Following its recommendations should ensure the association's smooth budgetary transitions from one fiscal year to the next, and either decrease or eliminate the need for "special assessments".

In addition, your reserve study serves a variety of useful purposes:

- Following the recommendations of a reserve study performed by a professional consultant can protect the Board of Directors in a community from personal liability concerning reserve components and reserve funding.
- A reserve analysis study is required by your accountant during the preparation of the association's annual audit.
- The reserve study is often requested by lending institutions during the process of loan applications, both for the community and, in many cases, the individual owners.
- Your Report is also a detailed inventory of the association's major assets and serves as a management tool for scheduling, coordinating and planning future repairs and replacements.
- Your Report is a tool that can assist the Board in fulfilling its legal and fiduciary obligations for maintaining the community in a state of good repair. If a community is operating on a special assessment basis, it cannot guarantee that an assessment, when needed, will be passed. Therefore, it cannot guarantee its ability to perform the required repairs or replacements to those major components for which the association is obligated.
- Since the reserve analysis study includes measurements and cost estimates of the client's assets, the detail reports may be used to evaluate the accuracy and price of contractor bids when assets are due to be repaired or replaced.
- The reserve study is an annual disclosure to the membership concerning the financial condition of the association, and may be used as a "consumers' guide" by prospective purchasers.

Tempe Villages HOA

FDRS Current Assessment Funding Model Summary

| | | Report Parameters | |
|---|---------------------------------------|---|--------------------------|
| Report Date | August 31, 2016 | Inflation Annual Assessment Increase | 3.00% 0.00% |
| Budget Year Beginning Budget Year Ending | January 01, 2016 December 31, 2016 | Interest Rate on Reserve Deposit Tax Rate on Interest Contingency | 1.00% 30.00% 3.00% |
| Total Units | 94 | 2016 Beginning Balance | \$107,635.00 |


Required annually Contribution \$276.60 per unit annually Average Net Annual Interest Earned Total annually Allocation to Reserves \$279.12 per unit annually \$26,000.00

 $\frac{\$236.98}{\$26,\!236.98}$

Tempe Villages HOA FDRS Current Assessment Funding Model Projection

Beginning Balance: \$107,635

| 0 | 8 | -) | | | Projected | Fully | |
|------|-----------|--------------|----------|--------------|------------|-----------|---------|
| | Current | Annual | Annual | Annual | Ending | Funded | Percent |
| Year | Cost | Contribution | Interest | Expenditures | Reserves | Reserves | Funded |
| | | | | | | | |
| 2016 | 748,325 | 26,000 | 237 | 99,780 | 34,092 | 531,328 | 6% |
| 2017 | 770,775 | 26,000 | | 61,373 | -1,281 | 555,187 | 0% |
| 2018 | 772,680 | 26,000 | | 46,627 | -21,907 | 562,100 | -4% |
| 2019 | 748,655 | 26,000 | | 38,060 | -33,967 | 570,796 | -6% |
| 2020 | 771,114 | 26,000 | | 70,806 | -78,773 | 564,176 | -14% |
| 2021 | 794,248 | 26,000 | | 869 | -53,642 | 630,935 | -9% |
| 2022 | 818,075 | 26,000 | | 70,079 | -97,721 | 630,483 | -15% |
| 2023 | 842,618 | 26,000 | | 116,715 | -188,436 | 583,526 | -32% |
| 2024 | 867,896 | 26,000 | | 104,861 | -267,297 | 550,190 | -49% |
| 2025 | 893,933 | 26,000 | | 117,356 | -358,653 | 506,095 | -71% |
| 2026 | 920,751 | 26,000 | | 116,146 | -448,799 | 465,042 | -97% |
| 2027 | 948,373 | 26,000 | | 208,673 | -631,472 | 333,616 | -189% |
| 2028 | 976,825 | 26,000 | | 79,985 | -685,457 | 333,007 | -206% |
| 2029 | 1,006,129 | 26,000 | | 8,738 | -668,195 | 407,987 | -164% |
| 2030 | 1,036,313 | 26,000 | | 143,545 | -785,740 | 348,459 | -225% |
| 2031 | 1,067,403 | 26,000 | | 33,006 | -792,745 | 403,391 | -197% |
| 2032 | 1,099,425 | 26,000 | | 25,435 | -792,180 | 470,130 | -169% |
| 2033 | 1,132,408 | 26,000 | | 33,768 | -799,948 | 532,706 | -150% |
| 2034 | 1,166,380 | 26,000 | | 27,494 | -801,442 | 606,126 | -132% |
| 2035 | 1,201,371 | 26,000 | | 66,475 | -841,917 | 644,135 | -131% |
| 2036 | 1,237,412 | 26,000 | | 24,617 | -840,534 | 729,681 | -115% |
| 2037 | 1,274,535 | 26,000 | | 211,702 | -1,026,236 | 627,671 | -163% |
| 2038 | 1,312,771 | 26,000 | | 13,001 | -1,013,237 | 730,277 | -139% |
| 2039 | 1,352,154 | 26,000 | | 4,441 | -991,677 | 847,701 | -117% |
| 2040 | 1,392,718 | 26,000 | | 110,645 | -1,076,322 | 862,162 | -125% |
| 2041 | 1,434,500 | 26,000 | | 12,458 | -1,062,780 | 981,373 | -108% |
| 2042 | 1,477,535 | 26,000 | | 11,322 | -1,048,102 | 1,108,518 | -95% |
| 2043 | 1,521,861 | 26,000 | | 33,653 | -1,055,755 | 1,219,737 | -87% |
| 2044 | 1,567,517 | 26,000 | | 368,112 | -1,397,867 | 992,868 | -141% |
| 2045 | 1,614,542 | 26,000 | | 233,249 | -1,605,116 | 901,708 | -178% |
| | | | | | | | |



The Current Assessment Funding Model is based on the <u>current</u> annual assessment, parameters, and reserve fund balance. Because it is calculated using the current annual assessment, it will give the accurate projection of how well the association is funded for the next 30 years of planned reserve expenditures.

Tempe Villages HOA

FDRS Alternate Funding Model 1 Summary

| | | Report Parameters |
|---|---------------------------------------|---|
| Report Date | August 31, 2016 | Inflation 3.00% |
| Budget Year Beginning Budget Year Ending | January 01, 2016 December 31, 2016 | Interest Rate on Reserve Deposit1.00%Tax Rate on Interest30.00%Contingency3.00% |
| Total Units | 94 | 2016 Beginning Balance \$107,635.00 |

Funding model based on the following contribution to the reserve fund:

- Funding in 2016 is based on current funding of \$26,000 or \$23.05 per unit/per month
- Funding in 2017 is increased to \$56,400 or \$50 per unit/per month
- Funding in 2018 is then increased to \$67,700 or \$60 per unit/per month
- Funding with automatic increase in 2019 is 5% annually

| Alternate Funding Model 1 Summary of Calculations | |
|---|-------------|
| Required annually Contribution \$276.60 per unit annually | \$26,000.00 |
| Average Net Annual Interest Earned | \$236.98 |
| Total annually Allocation to Reserves \$279.12 per unit annually | \$26,236.98 |

Tempe Villages HOA FDRS Alternate Funding Model 1 Projection

Beginning Balance: \$107,635

| U | 0 | , | | | Projected | Fully | |
|------|-----------|--------------|----------|--------------|-----------|-----------|---------|
| | Current | Annual | Annual | Annual | Ending | Funded | Percent |
| Year | Cost | Contribution | Interest | Expenditures | Reserves | Reserves | Funded |
| | | | | | | | |
| 2016 | 748,325 | 26,000 | 237 | 99,780 | 34,092 | 531,328 | 6% |
| 2017 | 770,775 | 56,400 | 204 | 61,373 | 29,323 | 555,187 | 5% |
| 2018 | 772,680 | 67,700 | 353 | 46,627 | 50,749 | 562,100 | 9% |
| 2019 | 748,655 | 67,700 | 563 | 38,060 | 80,953 | 570,796 | 14% |
| 2020 | 771,114 | 71,085 | 569 | 70,806 | 81,800 | 564,176 | 14% |
| 2021 | 794,248 | 74,639 | 1,089 | 869 | 156,659 | 630,935 | 25% |
| 2022 | 818,075 | 78,371 | 1,155 | 70,079 | 166,106 | 630,483 | 26% |
| 2023 | 842,618 | 82,290 | 922 | 116,715 | 132,603 | 583,526 | 23% |
| 2024 | 867,896 | 86,404 | 799 | 104,861 | 114,945 | 550,190 | 21% |
| 2025 | 893,933 | 90,724 | 618 | 117,356 | 88,932 | 506,095 | 18% |
| 2026 | 920,751 | 95,261 | 476 | 116,146 | 68,523 | 465,042 | 15% |
| 2027 | 948,373 | 100,024 | | 208,673 | -40,127 | 333,616 | -12% |
| 2028 | 976,825 | 105,025 | | 79,985 | -15,087 | 333,007 | -5% |
| 2029 | 1,006,129 | 110,276 | 605 | 8,738 | 87,057 | 407,987 | 21% |
| 2030 | 1,036,313 | 115,790 | 415 | 143,545 | 59,717 | 348,459 | 17% |
| 2031 | 1,067,403 | 121,579 | 1,038 | 33,006 | 149,329 | 403,391 | 37% |
| 2032 | 1,099,425 | 127,658 | 1,761 | 25,435 | 253,314 | 470,130 | 54% |
| 2033 | 1,132,408 | 134,041 | 2,475 | 33,768 | 356,062 | 532,706 | 67% |
| 2034 | 1,166,380 | 140,743 | 3,285 | 27,494 | 472,597 | 606,126 | 78% |
| 2035 | 1,201,371 | 147,781 | 3,877 | 66,475 | 557,779 | 644,135 | 87% |
| 2036 | 1,237,412 | 155,170 | 4,818 | 24,617 | 693,150 | 729,681 | 95% |
| 2037 | 1,274,535 | 162,928 | 4,511 | 211,702 | 648,887 | 627,671 | 103% |
| 2038 | 1,312,771 | 171,075 | 5,649 | 13,001 | 812,610 | 730,277 | 111% |
| 2039 | 1,352,154 | 179,628 | 6,915 | 4,441 | 994,712 | 847,701 | 117% |
| 2040 | 1,392,718 | 188,610 | 7,509 | 110,645 | 1,080,185 | 862,162 | 125% |
| 2041 | 1,434,500 | 198,040 | 8,860 | 12,458 | 1,274,628 | 981,373 | 130% |
| 2042 | 1,477,535 | 207,942 | 10,299 | 11,322 | 1,481,547 | 1,108,518 | 134% |
| 2043 | 1,521,861 | 218,339 | 11,664 | 33,653 | 1,677,897 | 1,219,737 | 138% |
| 2044 | 1,567,517 | 229,256 | 10,773 | 368,112 | 1,549,814 | 992,868 | 156% |
| 2045 | 1,614,542 | 240,719 | 10,901 | 233,249 | 1,568,185 | 901,708 | 174% |
| | | | | | | | |

| Description | Expenditures |
|--|--------------|
| Replacement Year 2016 | |
| Pools & Recreation Area | |
| Cedar Shake Shingles - Replace | 3,480 |
| Clubhouse & Pool Equipment Buildings - Paint | 2,000 |
| Pool Pump & Motor - Replace | 1,400 |
| Grounds | |
| Concrete - Repair & Replace | 750 |
| Buildings | |
| Buildings - Paint | 92,150 |
| Total for 2016 | \$99,780 |
| | , |
| Replacement Year 2017 | |
| Pools & Recreation Area | |
| Drinking Fountain - Replace | 618 |
| Ramadas - Paint | 5,150 |
| Spa Heater - Replace | 3,296 |
| Spa Pump & Motor - Replace | 2,060 |
| Tennis Court Chain Link Fencing - Repair | 7,725 |
| Tennis Courts - Repair & Resurface | 15,450 |
| Tennis Courts Lighting - Replace | 15,450 |
| Grounds | |
| Concrete - Repair & Replace | 772 |
| Buildings | |
| Storage Sheds - Replace | 5,150 |
| Walls & Fences | |
| Block Walls - Repair | 3,090 |
| Wrought Iron Fencing - Paint | 1,066 |
| Wrought Iron Fencing - Repair | 1,545 |
| Total for 2017 | \$61,373 |
| Replacement Year 2018 | |
| - | |
| Grounds | 796 |
| Concrete - Repair & Replace | /90 |
| Parking Areas | 15 071 |
| Asphalt - Slurry Seal | 45,831 |
| Total for 2018 | \$46,627 |

| Description | Expenditures |
|-------------------------------------|--------------|
| Replacement Year 2019 | |
| Grounds | |
| Concrete - Repair & Replace | 820 |
| Parking Areas | |
| Asphalt - Seal Coat | 15,735 |
| Carports - Paint | 8,392 |
| Walls & Fences | |
| Block Walls - Paint | 13,113 |
| Total for 2019 | \$38,060 |
| Replacement Year 2020 | |
| Pools & Recreation Area | |
| Pool Deck - Recoat | 35,454 |
| Pool Surface - Replace | 5,177 |
| Spa Surface - Replace | 518 |
| Grounds | |
| Concrete - Repair & Replace | 844 |
| Parking Areas | |
| Carports - Repair | 28,813 |
| Total for 2020 | \$70,806 |
| Replacement Year 2021 | |
| Grounds | |
| Concrete - Repair & Replace | 869 |
| Total for 2021 | \$869 |
| Replacement Year 2022 | |
| Pools & Recreation Area | |
| Ramada Roof Structure (1) - Replace | 6,114 |
| Ramada Roof Structure (2) - Replace | 19,487 |
| Ramada Roof Structure (3) - Replace | 19,821 |
| Spa Filter - Replace | 1,194 |
| Grounds | |
| Concrete - Repair & Replace | 896 |
| Parking Areas | |
| Asphalt - Seal Coat | 17,194 |
| | |

| Description | Expenditures |
|--|--------------|
| Replacement Year 2022 continued | |
| Walls & Fences | |
| Block Walls - Repair | 3,582 |
| Wrought Iron Fencing - Repair | 1,791 |
| Total for 2022 | \$70,079 |
| Replacement Year 2023 | |
| Pools & Recreation Area | |
| Clubhouse & Pool Equipment Buildings - Paint | 2,460 |
| Grounds | |
| Concrete - Repair & Replace | 922 |
| Buildings | |
| Buildings - Paint | 113,333 |
| Total for 2023 | \$116,715 |
| 10tai 101 2025 | \$110,713 |
| Replacement Year 2024 | |
| Pools & Recreation Area | |
| Ramadas - Paint | 6,334 |
| Tennis Courts - Resurface | 12,668 |
| Grounds | |
| Concrete - Repair & Replace | 950 |
| Buildings | |
| Buildings Roof Shingle - Replace - Phase 1 | 83,598 |
| Walls & Fences | |
| Wrought Iron Fencing - Paint | 1,311 |
| Total for 2024 | \$104,861 |
| Replacement Year 2025 | |
| Pools & Recreation Area | |
| Pool Benches - Replace | 5,219 |
| Grounds | , |
| Concrete - Repair & Replace | 979 |
| Information Sign - Replace | 783 |
| Irrigation Controllers - Replace | 5,480 |
| Buildings | , |
| Buildings Roof Shingle - Replace - Phase 2 | 86,106 |
| | |

| Description | Expenditures |
|---|----------------|
| Replacement Year 2025 continued | |
| Parking Areas | 10 700 |
| Asphalt - Seal Coat | 18,789 |
| Total for 2025 | \$117,356 |
| Replacement Year 2026 | |
| Grounds | |
| Concrete - Repair & Replace | 1,008 |
| Buildings Buildings Roof Shingle - Replace - Phase 3 | 88,690 |
| Parking Areas | |
| Carports - Paint | 10,321 |
| Walls & Fences | |
| Block Walls - Paint | 16,127 |
| Total for 2026 | \$116,146 |
| Replacement Year 2027 | |
| Pools & Recreation Area | |
| Pool Filter - Replace | 2,076 |
| Grounds | 1.000 |
| Concrete - Repair & Replace | 1,038 |
| Parking Areas | 100 220 |
| Asphalt - Overlay | 199,330 |
| Walls & Fences | 4 152 |
| Block Walls - Repair Wrought Iron Fencing - Repair | 4,153 2,076 |
| Total for 2027 | |
| Total for 2027 | \$208,673 |
| Replacement Year 2028 | |
| Pools & Recreation Area | |
| Pool Pump & Motor - Replace | 1,996 |
| Grounds | 1 0 4 0 |
| Concrete - Repair & Replace | 1,069 |
| Buildings Buildings Roof Tile - Replace | 56,389 |
| | 20,207 |

| Replacement Year 2028 continuedParking Areas Asphalt - Seal Coat20,531Total for 2028\$79,985 |
|---|
| Parking AreasAsphalt - Seal Coat20,531 |
| Asphalt - Seal Coat 20,531 |
| |
| |
| |
| Replacement Year 2029 |
| Pools & Recreation Area |
| Spa Heater - Replace 4,699 |
| Spa Pump & Motor - Replace 2,937 |
| Grounds |
| Concrete - Repair & Replace 1,101 |
| Total for 2029 \$8,738 |
| |
| Replacement Year 2030 |
| Pools & Recreation Area |
| Clubhouse & Pool Equipment Buildings - Paint 3,025 |
| Grounds |
| Concrete - Repair & Replace 1,134 |
| Buildings |
| Buildings - Paint 139,385 |
| Total for 2030 \$143,545 |
| |
| Replacement Year 2031 |
| Pools & Recreation Area |
| Ramadas - Paint 7,790 |
| Grounds |
| Concrete - Repair & Replace 1,168 |
| Parking Areas |
| Asphalt - Seal Coat 22,435 |
| Walls & Fences |
| Wrought Iron Fencing - Paint 1,612 |
| Total for 2031 \$33,006 |
| |
| Replacement Year 2032 |
| Pools & Recreation Area |
| Drinking Fountain - Replace 963 |

| Description | Expenditures |
|--|--------------------------|
| Replacement Year 2032 continued Tennis Courts - Resurface | 16,047 |
| Grounds Concrete - Repair & Replace | 1,204 |
| Walls & Fences Block Walls - Repair Wrought Iron Fencing - Repair | 4,814 2,407 |
| Total for 2032 | <u>\$25,435</u> |
| Replacement Year 2033 | |
| Grounds Concrete - Repair & Replace | 1,240 |
| Parking Areas Carports - Paint | 12,694 |
| Walls & Fences Block Walls - Paint | 19,834 |
| Total for 2033 | \$33,768 |
| Replacement Year 2034 | |
| Pools & Recreation Area Spa Filter - Replace | 1,702 |
| Grounds Concrete - Repair & Replace | 1,277 |
| Parking Areas Asphalt - Seal Coat | 24,515 |
| Total for 2034 | \$27,494 |
| Replacement Year 2035 | |
| Pools & Recreation Area Pool Deck - Recoat Pool Surface - Replace Spa Surface - Replace | 55,235 8,066 807 |
| Grounds Concrete - Repair & Replace | 1,315 |
| Information Sign - Replace Total for 2035 | 1,052 \$66,475 |

| Description | Expenditures |
|---|--------------|
| Replacement Year 2036 | |
| Pools & Recreation Area Cedar Shake Shingles - Replace | 6,285 |
| Grounds | |
| Concrete - Repair & Replace | 1,355 |
| Mailboxes - Replace | 16,977 |
| Total for 2036 | \$24,617 |
| Replacement Year 2037 | |
| Pools & Recreation Area Clubhouse & Pool Equipment Buildings - Paint | 3,721 |
| Grounds | -) - |
| Concrete - Repair & Replace | 1,395 |
| Buildings | |
| Buildings - Paint | 171,426 |
| Parking Areas | |
| Asphalt - Seal Coat | 26,788 |
| Walls & Fences Block Walls - Repair | 5,581 |
| Wrought Iron Fencing - Repair | 2,790 |
| Total for 2037 | \$211,702 |
| Replacement Year 2038 | |
| Pools & Recreation Area | |
| Ramadas - Paint | 9,581 |
| Grounds | |
| Concrete - Repair & Replace | 1,437 |
| Walls & Fences Wrought Iron Fencing - Paint | 1,983 |
| Total for 2038 | |
| 10tal 10F 2038 | \$13,001 |
| Replacement Year 2039 | |
| Pools & Recreation Area | |
| Pool Filter - Replace | 2,960 |

| Description | Expenditures |
|----------------------------------|--------------|
| Replacement Year 2039 continued | |
| Grounds | 1 400 |
| Concrete - Repair & Replace | 1,480 |
| Total for 2039 | \$4,441 |
| Replacement Year 2040 | |
| Pools & Recreation Area | |
| Pool Benches - Replace | 8,131 |
| Pool Pump & Motor - Replace | 2,846 |
| Tennis Courts - Resurface | 20,328 |
| Grounds | |
| Concrete - Repair & Replace | 1,525 |
| Irrigation Controllers - Replace | 8,538 |
| Parking Areas | 20.272 |
| Asphalt - Seal Coat | 29,272 |
| Carports - Paint | 15,612 |
| Walls & Fences | 24 204 |
| Block Walls - Paint | 24,394 |
| Total for 2040 | \$110,645 |
| Replacement Year 2041 | |
| Pools & Recreation Area | |
| Spa Heater - Replace | 6,700 |
| Spa Pump & Motor - Replace | 4,188 |
| Grounds | 1.570 |
| Concrete - Repair & Replace | 1,570 |
| Total for 2041 | \$12,458 |
| Replacement Year 2042 | |
| Grounds | |
| Concrete - Repair & Replace | 1,617 |
| Walls & Fences | |
| Block Walls - Repair | 6,470 |
| Wrought Iron Fencing - Repair | 3,235 |
| Total for 2042 | \$11,322 |

| Description | Expenditures |
|---|--------------|
| Replacement Year 2043 | |
| Grounds | |
| Concrete - Repair & Replace | 1,666 |
| Parking Areas | 31,987 |
| Asphalt - Seal Coat | |
| Total for 2043 | \$33,653 |
| Replacement Year 2044 | |
| Pools & Recreation Area | |
| Clubhouse & Pool Equipment Buildings - Paint | 4,576 |
| Grounds | |
| Concrete - Repair & Replace | 1,716 |
| Buildings | 210.022 |
| Buildings - Paint Buildings Reaf Shingle - Replace - Phase 1 | 210,833 |
| Buildings Roof Shingle - Replace - Phase 1 | 150,988 |
| Total for 2044 | \$368,112 |
| Replacement Year 2045 | |
| Pools & Recreation Area | |
| Ramadas - Paint | 11,783 |
| Grounds | |
| Concrete - Repair & Replace | 1,767 |
| Information Sign - Replace | 1,414 |
| Buildings Buildings Roof Shingle - Replace - Phase 2 | 155,518 |
| Parking Areas | 100,010 |
| Carports - Repair | 60,328 |
| Walls & Fences | |
| Wrought Iron Fencing - Paint | 2,439 |
| Total for 2045 | \$233,249 |

| Cedar Shake Shin | gles - Replace | 1,160 SF | @ \$3.00 |
|-------------------|-------------------------|-----------------------|------------|
| Asset I | D 1012 | Asset Cost | \$3,480.00 |
| | Pools & Recreation Area | Percent Replacement | 100% |
| | Roofing | Future Cost | \$3,480.00 |
| Placed in Service | ze July 1974 | Assigned Reserves | \$3,480.00 |
| Useful Li | fe 20 | - | |
| Replacement Yea | ur 2016 | Annual Assessment | \$39.56 |
| Remaining Li | fe 0 | Interest Contribution | \$0.28 |
| - | | Reserve Allocation | \$39.84 |



Poor condition. No signs of leaking but noticable movement away from roof. Our cost is based on replacing with a composite 20 year shingle.

Clubhouse & Pool Equipment Buildings - Paint

| Asset ID Pools | 1052 & Recreation Area | 1 LS Asset Cost Percent Replacement | @ \$2,000.00 \$2,000.00 100% |
|------------------------------------|-------------------------------|--|-------------------------------------|
| Placed in Service Useful Life | Painting January 1998 7 | Future Cost Assigned Reserves | \$2,000.00 \$2,000.00 |
| Replacement Year Remaining Life | 2016 0 | Annual Assessment Interest Contribution Reserve Allocation | \$46.32 <u>\$0.32</u> \$46.64 |

Clubhouse & Pool Equipment Buildings - Paint continued...



Fair to good condition. Cost to paint clubhouse and pool equipment building located in recreation/pool area. Estimate by Marcel Painting in Oct 2015. Last repaint date unknown.

| Drinking Fountain - Rep | lace | 1 Un | @ \$600.00 |
|-------------------------|-----------------|---------------------------|------------|
| Asset ID | 1011 | Asset Cost | \$600.00 |
| Pools & | Recreation Area | Percent Replacement | 100% |
| | Equipment | Future Cost | \$618.00 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 15 | | |
| Adjustment | 28 | Annual Assessment | \$83.20 |
| Replacement Year | 2017 | Interest Contribution | \$0.58 |
| Remaining Life | 1 | Reserve Allocation | \$83.78 |



Non usable condition. Broken and disconnected. Elkay.

| Pool Benches - Replace | | 4 EA | @ \$1,000.00 |
|------------------------|-------------------|---------------------------|--------------|
| Asset ID | 1024 | Asset Cost | \$4,000.00 |
| Pools & | & Recreation Area | Percent Replacement | 100% |
| | Furnishings | Future Cost | \$5,219.09 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 15 | | |
| Adjustment | 36 | Annual Assessment | \$75.91 |
| Replacement Year | 2025 | Interest Contribution | \$0.53 |
| Remaining Life | 9 | Reserve Allocation | \$76.44 |



Good condition. Replacement based on purchasing new thermoplastic coated 6' park benches.

| Pool Deck - Recoat | | 7,000 SF | @ \$4.50 |
|--------------------|-----------------------|-----------------------|-------------|
| Asset ID | 1023 | Asset Cost | \$31,500.00 |
| Poe | ols & Recreation Area | Percent Replacement | 100% |
| | Pool/Spa | Future Cost | \$35,453.53 |
| Placed in Service | January 2005 | Assigned Reserves | none |
| Useful Life | 15 | | |
| Replacement Year | 2020 | Annual Assessment | \$1,180.74 |
| Remaining Life | 4 | Interest Contribution | \$8.27 |
| | | Reserve Allocation | \$1,189.01 |

Pool Deck - Recoat continued...



Good to fair condition. Some limited cracking. Suggest cleaning. Date of last recoat unknown.

| Pool Filter - Replace | | 1 Un | @ \$1,500.00 |
|-----------------------|-------------------|-----------------------|--------------|
| | 1007 | | <u> </u> |
| Asset ID | 1006 | Asset Cost | \$1,500.00 |
| Pools | & Recreation Area | Percent Replacement | 100% |
| | Equipment | Future Cost | \$2,076.35 |
| Placed in Service | January 2015 | Assigned Reserves | none |
| Useful Life | 12 | | |
| Replacement Year | 2027 | Annual Assessment | \$24.53 |
| Remaining Life | 11 | Interest Contribution | \$0.17 |
| | | Reserve Allocation | \$24.71 |



Good condition. Triton II TR-140C. Replaced 1/1/2015

| Pool Pump & Motor - F | Replace | 1 Un | @ \$1,400.00 |
|-------------------------|--------------|---------------------------|--------------|
| Asset ID | 1055 | Asset Cost | \$1,400.00 |
| Pools & Recreation Area | | Percent Replacement | 100% |
| | Equipment | Future Cost | \$1,400.00 |
| Placed in Service | January 2004 | Assigned Reserves | \$1,400.00 |
| Useful Life | 12 | | |
| Replacement Year | 2016 | Annual Assessment | \$21.54 |
| Remaining Life | 0 | Interest Contribution | \$0.15 |
| | | Reserve Allocation | \$21.69 |



Poor condition. Purex Triton Whisperflow 3 hp. Noise emmiting. Last replacement date unknown.

| Pool Surface - Replace | | 1,150 SF | <i>(a)</i> \$4.00 |
|------------------------|-------------------|-----------------------|-------------------|
| Asset ID | 1020 | Asset Cost | \$4,600.00 |
| Pools | & Recreation Area | Percent Replacement | 100% |
| | Pool/Spa | Future Cost | \$5,177.34 |
| Placed in Service | January 2005 | Assigned Reserves | none |
| Useful Life | 15 | | |
| Replacement Year | 2020 | Annual Assessment | \$172.43 |
| Remaining Life | 4 | Interest Contribution | \$1.21 |
| | | Reserve Allocation | \$173.63 |

Pool Surface - Replace continued...



Good condtion. Plaster pool with tile. Last resurface unkown.

| Ramada Roof Structure | (1) - Replace | 256 SF | @ \$20.00 |
|-----------------------|-------------------|---------------------------|------------|
| Asset ID | 1016 | Asset Cost | \$5,120.00 |
| Pools & | & Recreation Area | Percent Replacement | 100% |
| | Roofing | Future Cost | \$6,113.55 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 30 | | |
| Adjustment | 18 | Annual Assessment | \$134.79 |
| Replacement Year | 2022 | Interest Contribution | \$0.94 |
| Remaining Life | 6 | Reserve Allocation | \$135.73 |



Good condition. Stucco posts with wood supports and metal slats. Ramada next to pool equipment building in pool recreation area. Estimate wood structure to last another 5 years so long as upkeep is maintained. Noted wood deteriorating from sun and weather exposure.

| Ramada Roof Structu | re (2) - Replace | 816 SF | @ \$20.00 |
|---------------------|----------------------|---------------------------|-------------|
| Asset ID | 1017 | Asset Cost | \$16,320.00 |
| Poo | ls & Recreation Area | Percent Replacement | 100% |
| | Roofing | Future Cost | \$19,486.93 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 30 | | |
| Adjustment | 18 | Annual Assessment | \$429.64 |
| Replacement Year | 2022 | Interest Contribution | \$3.01 |
| Remaining Life | 6 | Reserve Allocation | \$432.64 |



Good condition. Stucco posts with wood supports and metal slats. Ramada location is covering spa in pool recreation area. Estimate wood structure to last another 5 years so long as upkeep is maintained. Noted wood deteriorating from sun and weather exposure.

| Ramada Roof Structur | re (3) - Replace | 830 SF | @ \$20.00 |
|----------------------|---------------------|---------------------------|-------------|
| Asset ID | 1018 | Asset Cost | \$16,600.00 |
| Pool | s & Recreation Area | Percent Replacement | 100% |
| | Roofing | Future Cost | \$19,821.27 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 30 | | |
| Adjustment | 18 | Annual Assessment | \$437.01 |
| Replacement Year | 2022 | Interest Contribution | \$3.06 |
| Remaining Life | 6 | Reserve Allocation | \$440.07 |

Ramada Roof Structure (3) - Replace continued...



Good condition. Stucco posts with wood supports and metal slats. Ramada is at entrance to pool recreation area. Estimate wood structure to last another 5 years so long as upkeep is maintained. Noted wood deteriorating from sun and weather exposure.

| Ramadas - Paint | | 1 LS | @ \$5,000.00 |
|-------------------|---------------------|---------------------------|--------------|
| Asset ID | 1051 | Asset Cost | \$5,000.00 |
| Pool | s & Recreation Area | Percent Replacement | 100% |
| | Painting | Future Cost | \$5,150.00 |
| Placed in Service | July 1974 | Assigned Reserves | \$1,695.72 |
| Useful Life | 7 | | |
| Replacement Year | Deferred 2017 | Annual Assessment | \$463.42 |
| Remaining Life | 1 | Interest Contribution | \$15.11 |
| | | Reserve Allocation | \$478.54 |



Fair condition. Lump sum cost to paint 3 ramadas located in recreation/pool area. Estimate by Marcel Painting in Oct 2015. Last repaint date unknown.

Restrooms - Remodel

Asset ID 1013 Pools & Recreation Area Building Components Placed in Service July 1974 No Useful Life 2 LS Asset Cost Percent Replacement 100% Future Cost Assigned Reserves none

No Future Assessments



Good condition. Both the men's and womens restrooms contain (1) stool, (1) sink, tile floors, painted walls. Plumbing needs work as faucets are loose. This component covers entire replacement as needed for updating. Tile needs cleaning. Work that needs to be done is really maintenance work.

Shower - Remodel

Asset ID 1015 Pools & Recreation Area Building Components Placed in Service July 1974 No Useful Life

| 1 LS | |
|---------------------|------|
| Asset Cost | |
| Percent Replacement | 100% |
| Future Cost | |
| Assigned Reserves | none |

No Future Assessments



Good condition. Needs cleaning and paint. Ceramic tile floor to ceiling above pan.

| Spa Filter - Replace | | 1 Un | @ \$1,000.00 |
|----------------------|---------------------|-----------------------|--------------|
| Asset ID | 1009 | Asset Cost | \$1,000.00 |
| Pool | s & Recreation Area | Percent Replacement | 100% |
| | Equipment | Future Cost | \$1,194.05 |
| Placed in Service | January 2005 | Assigned Reserves | none |
| Useful Life | 12 | | |
| Adjustment | 5 | Annual Assessment | \$26.33 |
| Replacement Year | 2022 | Interest Contribution | \$0.18 |
| Remaining Life | 6 | Reserve Allocation | \$26.51 |



Good condition. Pentair FNS-48 DE. Diatomaceous earth filter. Last replacement unkown.

| Spa Heater - Replace |) | 1 Un | @ \$3,200.00 |
|----------------------|-------------------|---------------------------|--------------|
| Asset ID | 1010 | Asset Cost | \$3,200.00 |
| Pools | & Recreation Area | Percent Replacement | 100% |
| | Equipment | Future Cost | \$3,296.00 |
| Placed in Service | January 2016 | Assigned Reserves | none |
| Useful Life | 12 | | |
| Replacement Year | Deferred 2017 | Annual Assessment | \$443.71 |
| Remaining Life | 1 | Interest Contribution | \$3.11 |
| | | Reserve Allocation | \$446.82 |

Spa Heater - Replace continued...




New condition. Replaced 1/22/2016 by Aqua Patrol with Raypak 399BTU ASME NG Heater 009271 C-R406A-EN. 1 year manufacture warranty. Price includes labor.

| Spa Pump & Motor | - Replace | 2 Un | @ \$1,000.00 |
|-------------------|-----------------------|-----------------------|---------------|
| Asset ID | 1007 | Asset Cost | \$2,000.00 |
| | ols & Recreation Area | | \$2,000.00 |
| PO | | Percent Replacement | |
| | Equipment | Future Cost | \$2,060.00 |
| Placed in Service | January 2004 | Assigned Reserves | none |
| Useful Life | 12 | | |
| Replacement Year | Deferred 2017 | Annual Assessment | \$277.32 |
| Remaining Life | 1 | Interest Contribution | <u>\$1.94</u> |
| | | Reserve Allocation | \$279.26 |



Poor condition. Whisperflow 3/4 hp. Leaking. Suggest replacing along with spa motor. Last replacement unknown.

| Spa Surface - Replace | | 115 SF | @ \$4.00 |
|-----------------------|-------------------|-----------------------|----------|
| Asset ID | 1022 | Asset Cost | \$460.00 |
| Pools & | & Recreation Area | Percent Replacement | 100% |
| | Pool/Spa | Future Cost | \$517.73 |
| Placed in Service | January 2005 | Assigned Reserves | none |
| Useful Life | 15 | | |
| Replacement Year | 2020 | Annual Assessment | \$17.24 |
| Remaining Life | 4 | Interest Contribution | \$0.12 |
| | | Reserve Allocation | \$17.36 |



Good condtion. Plaster spa with tile. Last resurface unkown.

| Tennis Court Chai | n Link Fencing - Repair | 600 SF | @ \$12.50 |
|-------------------|-------------------------|---------------------------|------------|
| Asset II | 1032 | Asset Cost | \$7,500.00 |
| J | Pools & Recreation Area | Percent Replacement | 100% |
| | Fencing/Security | Future Cost | \$7,725.00 |
| Placed in Service | e July 1974 | Assigned Reserves | none |
| Useful Life | e 40 | | |
| Adjustmen | t 2 | Annual Assessment | \$1,039.95 |
| Replacement Year | Deferred 2017 | Interest Contribution | \$7.28 |
| Remaining Life | e 1 | Reserve Allocation | \$1,047.23 |

Tennis Court Chain Link Fencing - Repair continued...



Poor condition. Will need to replace most posts. Cost anticipates reusing some fencing.

| Tennis Courts - Repair | : & Resurface | 1 LS | @ \$15,000.00 |
|------------------------|---------------------|---------------------------|---------------|
| I | | | <u> </u> |
| Asset ID | 1053 | Asset Cost | \$15,000.00 |
| Pools | s & Recreation Area | Percent Replacement | 100% |
| | Tennis | Future Cost | \$15,450.00 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 1 | | |
| Replacement Year | Deferred 2017 | Annual Assessment | \$2,079.90 |
| Remaining Life | 1 | Interest Contribution | \$14.56 |
| | | Reserve Allocation | \$2,094.45 |
| | | | |



Poor condition. This is for a one time repair and resurface.

| Tennis Courts - Resurface | | 2 EA | @ \$5,000.00 |
|---------------------------|----------------|-----------------------|--------------|
| Asset ID | 1029 | Asset Cost | \$10,000.00 |
| Pools & R | ecreation Area | Percent Replacement | 100% |
| | Tennis | Future Cost | \$12,667.70 |
| Placed in Service | January 2015 | Assigned Reserves | none |
| Useful Life | 8 | | |
| Adjustment | 1 | Annual Assessment | \$208.00 |
| Replacement Year | 2024 | Interest Contribution | \$1.46 |
| Remaining Life | 8 | Reserve Allocation | \$209.46 |



This is for resurfacing every 8 years once repairs and resurfacing are complete.

| ing - Replace | 1 LS | @ \$15,000.00 |
|------------------------|--|--|
| 1030 | Asset Cost | \$15,000.00 |
| ools & Recreation Area | Percent Replacement | 100% |
| Lighting | Future Cost | \$15,450.00 |
| July 1974 | Assigned Reserves | none |
| 35 | | |
| 7 | Annual Assessment | \$2,079.90 |
| Deferred 2017 | Interest Contribution | \$14.56 |
| 1 | Reserve Allocation | \$2,094.45 |
| | ools & Recreation Area Lighting July 1974 35 7 | 1030Asset Cost1030Asset Costpols & Recreation AreaPercent ReplacementLightingFuture CostJuly 1974Assigned Reserves357Annual AssessmentDeferred 2017Interest Contribution |

Tennis Courts Lighting - Replace continued...



4 doubles and 8 single lights. Could not evaluate if lights are working so budgeted for full replacement.

| Water Heater - Replace | | 1 Un | @ \$2,500.00 |
|------------------------|-------------------|-----------------------|--------------|
| Asset ID | 1004 | Asset Cost | \$2,500.00 |
| Pools | & Recreation Area | Percent Replacement | 100% |
| | Equipment | Future Cost | \$2,813.77 |
| Placed in Service | January 2005 | Assigned Reserves | none |
| Useful Life | 15 | | |
| Replacement Year | 2020 | No Future Assessments | |
| Remaining Life | 4 | | |
| Remaining Life | 4 | | |



Stratford White 53 gallons. Could not access to confirm if in working condition. Last replacement unkown.

| Pools & Recreation Area - Total Current Cost | \$146,280 |
|--|-----------|
| Assigned Reserves | \$8,576 |
| Fully Funded Reserves | \$111,391 |

Backflow Preventer - Replace

Asset ID 1036 Grounds Placed in Service July 1974 No Useful Life

Asset Cost Percent Replacement Future Cost Assigned Reserves

100% none

No Future Assessments



| Concrete - Repair & | Replace | 1 LS | @ \$750.00 |
|---------------------|--------------------|---------------------------|------------|
| Asset ID | 1034 | Asset Cost | \$750.00 |
| | Grounds | Percent Replacement | 100% |
| | Grounds Components | Future Cost | \$750.00 |
| Placed in Service | July 1974 | Assigned Reserves | \$750.00 |
| Useful Life | 1 | | |
| Replacement Year | 2016 | Annual Assessment | \$103.99 |
| Remaining Life | 0 | Interest Contribution | \$0.73 |
| | | Reserve Allocation | \$104.72 |



Fair condition. Some tripping hazzards. Budget for annual concrete repair work.

| Granite - Replenish | | 1 LS | |
|-------------------------------------|--------------------|-----------------------|------|
| Asset ID | 1047 | Asset Cost | |
| | Grounds | Percent Replacement | 100% |
| | Grounds Components | Future Cost | |
| Placed in Service No Useful Life | July 1974 | Assigned Reserves | none |
| | | No Future Assessments | |
| | | | |

| [Information Sign - Rep] | lace | 1 LS | @ \$600.00 |
|---------------------------|--------------|---------------------------|------------|
| Asset ID | 1002 | Asset Cost | \$600.00 |
| | Grounds | Percent Replacement | 100% |
| | Signs | Future Cost | \$782.86 |
| Placed in Service | January 2015 | Assigned Reserves | none |
| Useful Life | 10 | | |
| Replacement Year | 2025 | Annual Assessment | \$11.39 |
| Remaining Life | 9 | Interest Contribution | \$0.08 |
| | | Reserve Allocation | \$11.47 |



Good condition.

| Information Signs - Pa | int | 1 LS | |
|------------------------|--|--|------|
| Asset ID | 1003 | Asset Cost | |
| | Grounds | Percent Replacement | 100% |
| | Painting | Future Cost | |
| Placed in Service | January 2008 | Assigned Reserves | none |
| No Useful Life | | | |
| | | No Future Assessments | |
| | empe Villages Townhomes 1988 Andrews Jones | Tempe Villages Townhomes 1601 - 1820 W. Village Way, Tempe, AZ | |

Included in exterior wall painting.

| Irrigation Controllers - | Replace | 6 EA | @ \$700.00 |
|--------------------------|--------------|---------------------------|------------|
| Asset ID | 1033 | Asset Cost | \$4,200.00 |
| | Grounds | Percent Replacement | 100% |
| | Equipment | Future Cost | \$5,480.05 |
| Placed in Service | January 2010 | Assigned Reserves | none |
| Useful Life | 15 | _ | |
| Replacement Year | 2025 | Annual Assessment | \$79.70 |
| Remaining Life | 9 | Interest Contribution | \$0.56 |
| - | | Reserve Allocation | \$80.26 |



There are a total of 6 timers on the property. 3 on the south side and 3 on the north side. Date

Irrigation Controllers - Replace continued...

last replaced unknown.

| Mailboxes - Replace | | 94 EA | @ \$100.00 |
|---------------------|-----------|---------------------------|-------------|
| Asset ID | 1041 | Asset Cost | \$9,400.00 |
| | Grounds | Percent Replacement | 100% |
| | Mailboxes | Future Cost | \$16,977.44 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 20 | | |
| Adjustment | 42 | Annual Assessment | \$106.86 |
| Replacement Year | 2036 | Interest Contribution | \$0.75 |
| Remaining Life | 20 | Reserve Allocation | \$107.61 |



Good condition. Some have been replaced.

| Monument - Replace | | 1 LS | |
|--------------------|--------------|---------------------|------|
| Asset ID | 1001 | Asset Cost | |
| | Grounds | Percent Replacement | 100% |
| | Signs | Future Cost | |
| Placed in Service | January 2008 | Assigned Reserves | none |
| No Useful Life | | | |

No Future Assessments

Monument - Replace continued...



Good condition. Metal letters painted. May need periodic painting to freshen appearance.

| Grounds - Total Current Cost | \$14,950 |
|------------------------------|----------|
| Assigned Reserves | \$750 |
| Fully Funded Reserves | \$8,858 |

| Buildings - Paint | | 1 LS | @ \$92,150.00 |
|-------------------|--------------|---------------------------|---------------|
| Asset ID | 1040 | Asset Cost | \$92,150.00 |
| | Buildings | Percent Replacement | 100% |
| | Painting | Future Cost | \$92,150.00 |
| Placed in Service | January 1999 | Assigned Reserves | \$92,150.00 |
| Useful Life | 7 | | |
| Replacement Year | 2016 | Annual Assessment | \$2,134.22 |
| Remaining Life | 0 | Interest Contribution | \$14.94 |
| | | Reserve Allocation | \$2,149.16 |



Fair to poor condition. Estimate by Marcel Painting in Oct 2015 includes stucco and fascia on all buildings. Last repaint date unknown.

Buildings Roof Shingle - Replace - Phase 1

| Asset ID | 1039 Buildings Roofing | 66,000 SF Asset Cost Percent Replacement Future Cost | @ \$3.00 \$65,993.40 33.33% \$83,598.46 |
|--|------------------------------|--|--|
| Placed in Service Useful Life | August 1998 20 | Assigned Reserves | none |
| Adjustment Replacement Year Remaining Life | 6 2024 8 | Annual Assessment Interest Contribution Reserve Allocation | \$1,372.66 <u>\$9.61</u> \$1,382.27 |

Buildings Roof Shingle - Replace - Phase 1 continued...



No roof leaks reported.

| Buildings Roof Shingle | - Replace - Phase 2 | | |
|------------------------|---------------------|---------------------------|-------------|
| | | 66,000 SF | @ \$3.00 |
| Asset ID | 1039 | Asset Cost | \$65,993.40 |
| | Buildings | Percent Replacement | 33.33% |
| | Roofing | Future Cost | \$86,106.42 |
| Placed in Service | August 1998 | Assigned Reserves | none |
| Useful Life | 20 | | |
| Adjustment | 7 | Annual Assessment | \$1,252.33 |
| Replacement Year | 2025 | Interest Contribution | \$8.77 |
| Remaining Life | 9 | Reserve Allocation | \$1,261.09 |
| | | | |



No roof leaks reported.

| Buildings Roof Shingle - Replace - Phase 3 | | | | |
|--|-------------|---------------------------|-------------|--|
| | | 66,000 SF | @ \$3.00 | |
| Asset ID | 1039 | Asset Cost | \$65,993.40 | |
| | Buildings | Percent Replacement | 33.33% | |
| | Roofing | Future Cost | \$88,689.61 | |
| Placed in Service | August 1998 | Assigned Reserves | none | |
| Useful Life | 20 | | | |
| Adjustment | 8 | Annual Assessment | \$1,156.82 | |
| Replacement Year | 2026 | Interest Contribution | \$8.10 | |
| Remaining Life | 10 | Reserve Allocation | \$1,164.92 | |
| | | | | |



No roof leaks reported.

| Buildings Roof Tile - Rej | place | 11,300 SF | <i>(a)</i> \$3.50 |
|---------------------------|-----------|---------------------------|-------------------|
| Asset ID | 1043 | Asset Cost | \$39,550.00 |
| | Buildings | Percent Replacement | 100% |
| | Roofing | Future Cost | \$56,388.84 |
| Placed in Service | July 1998 | Assigned Reserves | none |
| Useful Life | 30 | | |
| Replacement Year | 2028 | Annual Assessment | \$608.61 |
| Remaining Life | 12 | Interest Contribution | \$4.26 |
| | | Reserve Allocation | \$612.87 |

Buildings Roof Tile - Replace continued...



Appears to be in good condition. Tile material will last indefinately and underlayment will last approximately 30 years.

| Storage Sheds - Rep | place | 1 LS | @ \$5,000.00 |
|---------------------|---------------------|-----------------------|--------------|
| Asset ID | 1042 | Asset Cost | \$5,000.00 |
| | Buildings | Percent Replacement | 100% |
| | Building Components | Future Cost | \$5,150.00 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 5 | | |
| Replacement Year | Deferred 2017 | Annual Assessment | \$693.30 |
| Remaining Life | 1 | Interest Contribution | \$4.85 |
| | | Reserve Allocation | \$698.15 |



Replaced on as needed basis. This component reserves for \$5000 a year on a non recurring 5 year basis.

| Buildings - Total Current Cost | \$334,680 |
|---------------------------------------|-----------|
| Assigned Reserves | \$92,150 |
| Fully Funded Reserves | \$252,154 |

| Asphalt - Overlay | | 96,000 SF | @ \$1.50 |
|-------------------|-----------------|-----------------------|--------------|
| Asset ID | 1054 | Asset Cost | \$144,000.00 |
| | Parking Areas | Percent Replacement | 100% |
| | Streets/Asphalt | Future Cost | \$199,329.68 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 25 | | |
| Adjustment | 28 | Annual Assessment | \$2,355.26 |
| Replacement Year | 2027 | Interest Contribution | \$16.49 |
| Remaining Life | 11 | Reserve Allocation | \$2,371.75 |



Poor to fair condition.

7

| Asphalt - Seal Coat | | 96,000 SF | @ \$0.15 |
|---------------------|-----------------|---------------------------|-------------|
| Asset ID | 1038 | Asset Cost | \$14,400.00 |
| | Parking Areas | Percent Replacement | 100% |
| | Streets/Asphalt | Future Cost | \$15,735.27 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 3 | | |
| Adjustment | 42 | Annual Assessment | \$701.18 |
| Replacement Year | 2019 | Interest Contribution | \$4.91 |
| Remaining Life | 3 | Reserve Allocation | \$706.09 |
| | | | |

Asphalt - Seal Coat continued...



Poor to fair condition.

| Asphalt - Slurry Seal | | 96,000 SF | <i>(a)</i> \$0.45 |
|-----------------------|-----------------|---------------------------|-------------------|
| Asset ID | 1037 | Asset Cost | \$43,200.00 |
| | Parking Areas | Percent Replacement | 100% |
| | Streets/Asphalt | Future Cost | \$45,830.88 |
| Placed in Service | December 2015 | Assigned Reserves | none |
| Useful Life | 3 | | |
| Replacement Year | 2018 | Annual Assessment | \$3,074.14 |
| Remaining Life | 2 | Interest Contribution | \$21.52 |
| | | Reserve Allocation | \$3,095.66 |



Poor to Fair condition. Recommend sullry seal to extend the life of the pavement. Should include crack sealing prior to slurry seal. One time application.

| Carports - Repair | | 12,800 SF | @ \$2.00 |
|-------------------|--------------------|---------------------------|-------------|
| Asset ID | 1044 | Asset Cost | \$25,600.00 |
| | Parking Areas | Percent Replacement | 100% |
| | Parking Structures | Future Cost | \$28,813.03 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 25 | | |
| Adjustment | 21 | Annual Assessment | \$959.59 |
| Replacement Year | 2020 | Interest Contribution | \$6.72 |
| Remaining Life | 4 | Reserve Allocation | \$966.30 |



Roof material is an asphalt rolled material.

| Carports - Paint | | 12,800 SF | <i>(a)</i> \$0.60 |
|-------------------|---------------|---------------------------|-------------------|
| Asset ID | 1045 | Asset Cost | \$7,680.00 |
| | Parking Areas | Percent Replacement | 100% |
| | Painting | Future Cost | \$8,392.14 |
| Placed in Service | January 2012 | Assigned Reserves | none |
| Useful Life | 7 | | |
| Replacement Year | 2019 | Annual Assessment | \$373.96 |
| Remaining Life | 3 | Interest Contribution | \$2.62 |
| | | Reserve Allocation | \$376.58 |

Carports - Paint continued...



Good condition except where wood exposed (showing dry rot) on ends protruding from Asphalt roofs.

| Parking Areas - Total Current Cost | \$234,880 |
|------------------------------------|-----------|
| Assigned Reserves | \$0 |
| Fully Funded Reserves | \$169,716 |

| Block Walls - Paint |) | 20,000 SF | @ \$0.60 |
|---------------------|----------------|---------------------------|-------------|
| Asset ID | 1027 | Asset Cost | \$12,000.00 |
| | Walls & Fences | Percent Replacement | 100% |
| | Walls | Future Cost | \$13,112.72 |
| Placed in Service | January 2005 | Assigned Reserves | none |
| Useful Life | 7 | | |
| Adjustment | 7 | Annual Assessment | \$584.32 |
| Replacement Year | 2019 | Interest Contribution | \$4.09 |
| Remaining Life | 3 | Reserve Allocation | \$588.41 |



Good to fair condition. Some cracking and poor paint on interior walls at pool recreation area. Outside walls in surrounding community good condition. Last repaint date unknown.

| Block Walls - Repair | | 1 LS | @ \$3,000.00 |
|----------------------|----------------|-----------------------|----------------|
| Asset ID | 1028 | Asset Cost | \$3,000.00 |
| | Walls & Fences | Percent Replacement | 100% |
| | Walls | Future Cost | \$3,090.00 |
| Placed in Service | July 1974 | Assigned Reserves | \$2,930.23 |
| Useful Life | 5 | | |
| Adjustment | 37 | Annual Assessment | \$18.75 |
| Replacement Year | Deferred 2017 | Interest Contribution | <u>\$20.64</u> |
| Remaining Life | 1 | Reserve Allocation | \$39.39 |

Block Walls - Repair continued...



Good to fair condition. Some cracked and poor paint on interior walls at pool recreation area. Outside walls in surrounding community good condition. A budget for making wall repairs on a 5 year recurring schedule with approximate replacement of 1%. Total of approximately 20000 sf.

| Wrought Iron Fencing - Paint | | 1,150 SF | @ \$0.90 |
|------------------------------|------------------|---------------------------|------------|
| Asset ID | 1025 | Asset Cost | \$1,035.00 |
| | Walls & Fences | Percent Replacement | 100% |
| | Fencing/Security | Future Cost | \$1,066.05 |
| Placed in Service | January 1998 | Assigned Reserves | none |
| Useful Life | 7 | | |
| Adjustment | 12 | Annual Assessment | \$143.51 |
| Replacement Year | 2017 | Interest Contribution | \$1.00 |
| Remaining Life | 1 | Reserve Allocation | \$144.52 |
| | | | |



Poor condition. Surrounding pool recreation area. Rust and detrioration evidient where spray irrigation hits. Last repaint date unknown.

| Wrought Iron Fencing | - Repair | 1 LS | @ \$1,500.00 |
|----------------------|------------------|---------------------------|--------------|
| Asset ID | 1026 | Asset Cost | \$1,500.00 |
| | Walls & Fences | Percent Replacement | 100% |
| | Fencing/Security | Future Cost | \$1,545.00 |
| Placed in Service | July 1974 | Assigned Reserves | none |
| Useful Life | 5 | | |
| Adjustment | 38 | Annual Assessment | \$207.99 |
| Replacement Year | 2017 | Interest Contribution | \$1.46 |
| Remaining Life | 1 | Reserve Allocation | \$209.45 |



Good to fair condition. Some rusting visable at pool recreation area with some rusted out areas where irrigation hits. A budget for making wall repairs on a 5 year recurring schedule with approximate replacement of 5%. Total of approximately at approximately 1150 sf.

| Walls & Fences - Total Current Cost | \$17,535 |
|-------------------------------------|----------|
| Assigned Reserves | \$2,930 |
| Fully Funded Reserves | \$14,804 |

Detail Report Summary

Total of All Assets

| Assigned Reserves | \$104,405.95 |
|---------------------|--------------|
| Annual Contribution | \$25,220.00 |
| Annual Interest | \$208.92 |
| Annual Allocation | \$25,428.92 |

Contingency at 3.00%

| Assigned Reserves | \$3,229.05 |
|---------------------|------------|
| Annual Contribution | \$780.00 |
| Annual Interest | \$6.46 |
| Annual Allocation | \$786.46 |

Grand Total

| Assigned Reserves | \$107,635.00 |
|---------------------|--------------|
| Annual Contribution | \$26,000.00 |
| Annual Interest | \$215.38 |
| Annual Allocation | \$26,215.38 |

Tempe Villages HOA FDRS Category Detail Index

| Asset I | DDescription | Replacement | Page |
|---------|--|-------------|------|
| Pools & | & Recreation Area | | |
| 1012 | Cedar Shake Shingles - Replace | 2016 | 2-15 |
| 1052 | Clubhouse & Pool Equipment Buildings - Paint | 2016 | 2-15 |
| 1011 | Drinking Fountain - Replace | 2017 | 2-16 |
| 1024 | Pool Benches - Replace | 2025 | 2-17 |
| 1023 | Pool Deck - Recoat | 2020 | 2-17 |
| 1006 | Pool Filter - Replace | 2027 | 2-18 |
| 1055 | Pool Pump & Motor - Replace | 2016 | 2-19 |
| 1020 | Pool Surface - Replace | 2020 | 2-19 |
| 1016 | Ramada Roof Structure (1) - Replace | 2022 | 2-20 |
| 1017 | Ramada Roof Structure (2) - Replace | 2022 | 2-21 |
| 1018 | Ramada Roof Structure (3) - Replace | 2022 | 2-21 |
| 1051 | Ramadas - Paint | 2017 | 2-22 |
| 1013 | Restrooms - Remodel | Unfunded | 2-23 |
| 1015 | Shower - Remodel | Unfunded | 2-23 |
| 1009 | Spa Filter - Replace | 2022 | 2-24 |
| 1010 | Spa Heater - Replace | 2017 | 2-24 |
| 1007 | Spa Pump & Motor - Replace | 2017 | 2-25 |
| 1022 | Spa Surface - Replace | 2020 | 2-26 |
| 1032 | Tennis Court Chain Link Fencing - Repair | 2017 | 2-26 |
| 1053 | Tennis Courts - Repair & Resurface | 2017 | 2-27 |
| 1029 | Tennis Courts - Resurface | 2024 | 2-28 |
| 1030 | Tennis Courts Lighting - Replace | 2017 | 2-28 |
| 1004 | Water Heater - Replace | Unfunded | 2-29 |
| Groun | ds | | |
| 1036 | Backflow Preventer - Replace | Unfunded | 2-30 |
| 1034 | Concrete - Repair & Replace | 2016 | 2-30 |
| 1047 | Granite - Replenish | Unfunded | 2-31 |
| 1002 | Information Sign - Replace | 2025 | 2-31 |
| 1003 | Information Signs - Paint | Unfunded | 2-32 |
| 1033 | Irrigation Controllers - Replace | 2025 | 2-32 |
| 1041 | Mailboxes - Replace | 2036 | 2-33 |
| 1001 | Monument - Replace | Unfunded | 2-33 |
| Buildir | 105 | | |
| 1040 | Buildings - Paint | 2016 | 2-35 |
| 1040 | Buildings Roof Shingle - Replace - Phase 1 | 2010 | 2-35 |
| | | | |

Tempe Villages HOA FDRS Category Detail Index

| Asset II | DDescription | Replacement | Page |
|----------|--|-------------|------|
| Buildin | gs Continued | | |
| 1039 | Buildings Roof Shingle - Replace - Phase 2 | 2025 | 2-36 |
| 1039 | Buildings Roof Shingle - Replace - Phase 3 | 2026 | 2-37 |
| 1043 | Buildings Roof Tile - Replace | 2028 | 2-37 |
| 1042 | Storage Sheds - Replace | 2017 | 2-38 |
| Parkin | g Areas | | |
| 1054 | Asphalt - Overlay | 2027 | 2-39 |
| 1038 | Asphalt - Seal Coat | 2019 | 2-39 |
| 1037 | Asphalt - Slurry Seal | 2018 | 2-40 |
| 1044 | Carports - Repair | 2020 | 2-41 |
| 1045 | Carports - Paint | 2019 | 2-41 |
| Walls & | & Fences | | |
| 1027 | Block Walls - Paint | 2019 | 2-43 |
| 1028 | Block Walls - Repair | 2017 | 2-43 |
| 1025 | Wrought Iron Fencing - Paint | 2017 | 2-44 |
| 1026 | Wrought Iron Fencing - Repair | 2017 | 2-45 |
| | Total Funded Assets | 39 | |
| | Total Unfunded Assets | _7 | |
| | Total Assets | 46 | |

| | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 |
|--|--------------|--------|------|------|--------|------|--------|-------|--------|-------|
| Description | | | | | | | | | | |
| Pools & Recreation Area | | | | | | | | | | |
| Cedar Shake Shingles - Replace | 3,480 | | | | | | | | | |
| Clubhouse & Pool Equipment Buildings - Paint | 2,000 | | | | | | | 2,460 | | |
| Drinking Fountain - Replace | | 618 | | | | | | | | |
| Pool Benches - Replace | | | | | | | | | | 5,219 |
| Pool Deck - Recoat | | | | | 35,454 | | | | | |
| Pool Filter - Replace | | | | | | | | | | |
| Pool Pump & Motor - Replace | 1,400 | | | | | | | | | |
| Pool Surface - Replace | | | | | 5,177 | | | | | |
| Ramada Roof Structure (1) - Replace | | | | | | | 6,114 | | | |
| Ramada Roof Structure (2) - Replace | | | | | | | 19,487 | | | |
| Ramada Roof Structure (3) - Replace | | | | | | | 19,821 | | | |
| Ramadas - Paint | | 5,150 | | | | | | | 6,334 | |
| Restrooms - Remodel | Unfunded | | | | | | | | | |
| Shower - Remodel | Unfunded | | | | | | 1 104 | | | |
| Spa Filter - Replace | | 2 200 | | | | | 1,194 | | | |
| Spa Heater - Replace | | 3,296 | | | | | | | | |
| Spa Pump & Motor - Replace | | 2,060 | | | 518 | | | | | |
| Spa Surface - Replace | | 7,725 | | | 518 | | | | | |
| Tennis Court Chain Link Fencing - Repair Tennis Courts - Repair & Resurface | | 15,450 | | | | | | | | |
| Tennis Courts - Resurface | | 15,450 | | | | | | | 12,668 | |
| Tennis Courts Lighting - Replace | | 15,450 | | | | | | | 12,008 | |
| Water Heater - Replace | Unfunded | 15,450 | | | | | | | | |
| Pools & Recreation Area Total: | <u>6,880</u> | 49,749 | | | 41,149 | | 46,616 | 2,460 | 19,002 | 5,219 |
| | 0,000 | | | | 41,142 | | 40,010 | 2,400 | 17,002 | 5,217 |
| Grounds | | | | | | | | | | |
| Backflow Preventer - Replace | Unfunded | | | | | | | | | |
| Concrete - Repair & Replace | 750 | 772 | 796 | 820 | 844 | 869 | 896 | 922 | 950 | 979 |
| Granite - Replenish | Unfunded | | | | | | | | | |
| Information Sign - Replace | | | | | | | | | | 783 |
| Information Signs - Paint | Unfunded | | | | | | | | | |
| Irrigation Controllers - Replace | | | | | | | | | | 5,480 |
| Mailboxes - Replace | _ | | | | | | | | | |
| Monument - Replace | Unfunded | | | | | | | | | |
| Grounds Total: | 750 | 772 | 796 | 820 | 844 | 869 | 896 | 922 | 950 | 7,241 |

FDReserve Studies, LLC • 602-740-8730 PAGE 2-49

| | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 | 2024 | 2025 |
|--|--------|--------|--------|--------|--------|------|--------|---------|---------|---------|
| Description | | | | | | | | | | |
| Buildings | | | | | | | | | | |
| Buildings - Paint | 92,150 | | | | | | | 113,333 | | |
| Buildings Roof Shingle - Replace - Phase 1 | | | | | | | | | 83,598 | |
| Buildings Roof Shingle - Replace - Phase 2 | | | | | | | | | | 86,106 |
| Buildings Roof Shingle - Replace - Phase 3 | | | | | | | | | | |
| Buildings Roof Tile - Replace | | | | | | | | | | |
| Storage Sheds - Replace | | 5,150 | | | | | | | | |
| Buildings Total: | 92,150 | 5,150 | | | | | | 113,333 | 83,598 | 86,106 |
| Parking Areas | | | | | | | | | | |
| Asphalt - Overlay | | | | | | | | | | |
| Asphalt - Seal Coat | | | | 15,735 | | | 17,194 | | | 18,789 |
| Asphalt - Slurry Seal | | | 45,831 | | | | | | | |
| Carports - Repair | | | | | 28,813 | | | | | |
| Carports - Paint | | | | 8,392 | | | | | | |
| Parking Areas Total: | | | 45,831 | 24,127 | 28,813 | | 17,194 | | | 18,789 |
| Walls & Fences | | | | | | | | | | |
| Block Walls - Paint | | | | 13,113 | | | | | | |
| Block Walls - Repair | | 3,090 | | , | | | 3,582 | | | |
| Wrought Iron Fencing - Paint | | 1,066 | | | | | | | 1,311 | |
| Wrought Iron Fencing - Repair | | 1,545 | | | | | 1,791 | | | |
| Walls & Fences Total: | | 5,701 | | 13,113 | | | 5,373 | | 1,311 | |
| Year Total: | 99,780 | 61,373 | 46,627 | 38,060 | 70,806 | 869 | 70,079 | 116,715 | 104,861 | 117,356 |

| | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 |
|--|-----------|-------|-------|-------|-------|-------|--------|-------|-------|--------|
| Description | | | | | | | | | | |
| Pools & Recreation Area | | | | | | | | | | |
| Cedar Shake Shingles - Replace | | | | | | | | | | |
| Clubhouse & Pool Equipment Buildings - Paint | | | | | 3,025 | | | | | |
| Drinking Fountain - Replace | | | | | , | | 963 | | | |
| Pool Benches - Replace | | | | | | | | | | |
| Pool Deck - Recoat | | | | | | | | | | 55,235 |
| Pool Filter - Replace | | 2,076 | | | | | | | | |
| Pool Pump & Motor - Replace | | | 1,996 | | | | | | | |
| Pool Surface - Replace | | | | | | | | | | 8,066 |
| Ramada Roof Structure (1) - Replace | | | | | | | | | | |
| Ramada Roof Structure (2) - Replace | | | | | | | | | | |
| Ramada Roof Structure (3) - Replace | | | | | | | | | | |
| Ramadas - Paint | | | | | | 7,790 | | | | |
| Restrooms - Remodel | Unfunded | | | | | | | | | |
| Shower - Remodel | Unfunded | | | | | | | | | |
| Spa Filter - Replace | | | | | | | | | 1,702 | |
| Spa Heater - Replace | | | | 4,699 | | | | | | |
| Spa Pump & Motor - Replace | | | | 2,937 | | | | | | 0.07 |
| Spa Surface - Replace | | | | | | | | | | 807 |
| Tennis Court Chain Link Fencing - Repair | | | | | | | | | | |
| Tennis Courts - Repair & Resurface | | | | | | | 16047 | | | |
| Tennis Courts - Resurface | | | | | | | 16,047 | | | |
| Tennis Courts Lighting - Replace Water Heater - Replace | Unfounded | | | | | | | | | |
| Pools & Recreation Area Total: | Unfunded | 2,076 | 1,996 | 7,636 | 3,025 | 7,790 | 17,010 | | 1,702 | 64,108 |
| roois & Recreation Area Total: | | 2,070 | 1,990 | 7,030 | 3,025 | 7,790 | 17,010 | | 1,/02 | 04,108 |
| Grounds | | | | | | | | | | |
| Backflow Preventer - Replace | Unfunded | | | | | | | | | |
| Concrete - Repair & Replace | 1,008 | 1,038 | 1,069 | 1,101 | 1,134 | 1,168 | 1,204 | 1,240 | 1,277 | 1,315 |
| Granite - Replenish | Unfunded | | | | | | | | | |
| Information Sign - Replace | | | | | | | | | | 1,052 |
| Information Signs - Paint | Unfunded | | | | | | | | | |
| Irrigation Controllers - Replace | | | | | | | | | | |
| Mailboxes - Replace | | | | | | | | | | |
| Monument - Replace | Unfunded | | | | | | | | | |
| Grounds Total: | 1,008 | 1,038 | 1,069 | 1,101 | 1,134 | 1,168 | 1,204 | 1,240 | 1,277 | 2,367 |
| | | | | | | | | | | |

| | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 |
|--|---------|---------|--------|-------|---------|--------|--------|--------|--------|--------|
| Description | | | | | | | | | | |
| Buildings | | | | | | | | | | |
| Buildings - Paint | | | | | 139,385 | | | | | |
| Buildings Roof Shingle - Replace - Phase 1 | | | | | | | | | | |
| Buildings Roof Shingle - Replace - Phase 2 | | | | | | | | | | |
| Buildings Roof Shingle - Replace - Phase 3 | 88,690 | | | | | | | | | |
| Buildings Roof Tile - Replace | | | 56,389 | | | | | | | |
| Storage Sheds - Replace | | | | | 100.007 | | | | | |
| Buildings Total: | 88,690 | | 56,389 | | 139,385 | | | | | |
| Parking Areas | | | | | | | | | | |
| Asphalt - Overlay | | 199,330 | | | | | | | | |
| Asphalt - Seal Coat | | | 20,531 | | | 22,435 | | | 24,515 | |
| Asphalt - Slurry Seal | | | | | | | | | | |
| Carports - Repair | | | | | | | | | | |
| Carports - Paint | 10,321 | | | | | | | 12,694 | | |
| Parking Areas Total: | 10,321 | 199,330 | 20,531 | | | 22,435 | | 12,694 | 24,515 | |
| Walls & Fences | | | | | | | | | | |
| Block Walls - Paint | 16,127 | | | | | | | 19,834 | | |
| Block Walls - Repair | | 4,153 | | | | | 4,814 | | | |
| Wrought Iron Fencing - Paint | | | | | | 1,612 | | | | |
| Wrought Iron Fencing - Repair | | 2,076 | | | | | 2,407 | | | |
| Walls & Fences Total: | 16,127 | 6,229 | | | | 1,612 | 7,221 | 19,834 | | _ |
| Year Total: | 116,146 | 208,673 | 79,985 | 8,738 | 143,545 | 33,006 | 25,435 | 33,768 | 27,494 | 66,475 |

| | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 |
|--|----------|-------|-------|-------|--------|--------|-------|-------|-------|--------|
| Description | | | | | | | | | | |
| Pools & Recreation Area | | | | | | | | | | |
| Cedar Shake Shingles - Replace | 6,285 | | | | | | | | | |
| Clubhouse & Pool Equipment Buildings - Paint | , | 3,721 | | | | | | | 4,576 | |
| Drinking Fountain - Replace | | , | | | | | | | , | |
| Pool Benches - Replace | | | | | 8,131 | | | | | |
| Pool Deck - Recoat | | | | | | | | | | |
| Pool Filter - Replace | | | | 2,960 | | | | | | |
| Pool Pump & Motor - Replace | | | | | 2,846 | | | | | |
| Pool Surface - Replace | | | | | | | | | | |
| Ramada Roof Structure (1) - Replace | | | | | | | | | | |
| Ramada Roof Structure (2) - Replace | | | | | | | | | | |
| Ramada Roof Structure (3) - Replace | | | | | | | | | | |
| Ramadas - Paint | | | 9,581 | | | | | | | 11,783 |
| Restrooms - Remodel | Unfunded | | | | | | | | | |
| Shower - Remodel | Unfunded | | | | | | | | | |
| Spa Filter - Replace | | | | | | | | | | |
| Spa Heater - Replace | | | | | | 6,700 | | | | |
| Spa Pump & Motor - Replace | | | | | | 4,188 | | | | |
| Spa Surface - Replace | | | | | | | | | | |
| Tennis Court Chain Link Fencing - Repair | | | | | | | | | | |
| Tennis Courts - Repair & Resurface | | | | | | | | | | |
| Tennis Courts - Resurface | | | | | 20,328 | | | | | |
| Tennis Courts Lighting - Replace | | | | | | | | | | |
| Water Heater - Replace | Unfunded | | | | | | | | | |
| Pools & Recreation Area Total: | 6,285 | 3,721 | 9,581 | 2,960 | 31,305 | 10,888 | | | 4,576 | 11,783 |
| Grounds | | | | | | | | | | |
| Backflow Preventer - Replace | Unfunded | | | | | | | | | |
| Concrete - Repair & Replace | 1,355 | 1,395 | 1,437 | 1,480 | 1,525 | 1,570 | 1,617 | 1,666 | 1,716 | 1,767 |
| Granite - Replenish | Unfunded | 1,595 | 1,157 | 1,100 | 1,020 | 1,070 | 1,017 | 1,000 | 1,710 | 1,707 |
| Information Sign - Replace | onjunaca | | | | | | | | | 1,414 |
| Information Signs - Paint | Unfunded | | | | | | | | | _, |
| Irrigation Controllers - Replace | | | | | 8,538 | | | | | |
| Mailboxes - Replace | 16,977 | | | | , · | | | | | |
| Monument - Replace | Unfunded | | | | | | | | | |
| Grounds Total: | 18,332 | 1,395 | 1,437 | 1,480 | 10,062 | 1,570 | 1,617 | 1,666 | 1,716 | 3,181 |

FDReserve Studies, LLC • 602-740-8730 PAGE 2-53

| | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 |
|--|--------|---------|--------|-------|---------|--------|--------|--------|---------|---------|
| Description | | | | | | | | | | |
| Buildings | | | | | | | | | | |
| Buildings - Paint | | 171,426 | | | | | | | 210,833 | |
| Buildings Roof Shingle - Replace - Phase 1 | | | | | | | | | 150,988 | |
| Buildings Roof Shingle - Replace - Phase 2 | | | | | | | | | | 155,518 |
| Buildings Roof Shingle - Replace - Phase 3 | | | | | | | | | | |
| Buildings Roof Tile - Replace | | | | | | | | | | |
| Storage Sheds - Replace | | | | | | | | | | |
| Buildings Total: | | 171,426 | | | | | | | 361,821 | 155,518 |
| Parking Areas | | | | | | | | | | |
| Asphalt - Overlay | | | | | | | | | | |
| Asphalt - Seal Coat | | 26,788 | | | 29,272 | | | 31,987 | | |
| Asphalt - Slurry Seal | | | | | | | | | | |
| Carports - Repair | | | | | | | | | | 60,328 |
| Carports - Paint | | | | | 15,612 | | | | | |
| Parking Areas Total: | | 26,788 | | | 44,884 | | | 31,987 | | 60,328 |
| Walls & Fences | | | | | | | | | | |
| Block Walls - Paint | | | | | 24,394 | | | | | |
| Block Walls - Repair | | 5,581 | | | , | | 6,470 | | | |
| Wrought Iron Fencing - Paint | | | 1,983 | | | | | | | 2,439 |
| Wrought Iron Fencing - Repair | | 2,790 | | | | | 3,235 | | | |
| Walls & Fences Total: | | 8,371 | 1,983 | | 24,394 | | 9,705 | | | 2,439 |
| Year Total: | 24,617 | 211,702 | 13,001 | 4,441 | 110,645 | 12,458 | 11,322 | 33,653 | 368,112 | 233,249 |