

RESERVE ANALYSIS REPORT

Artesa

Laveen, Arizona

Version 003

February 25, 2022



ADVANCED RESERVE SOLUTIONS

2761 E. Bridgeport Pkwy - Gilbert, AZ 85295

Email: tthompson@arsinc.com

Phone (480) 473-7643

www.arsinc.com

© 1997 - 2021

ADVANCED RESERVE SOLUTIONS, INC.

All Rights Reserved.

Artesa

Table of Contents

| | Page |
|---------------------------------------|-------------|
| Preface | i |
| Executive Summary | 1 |
| Distribution of Current Reserve Funds | 2 |
| Component Summary | 3 |
| Projections | 5 |
| Projection Charts | 6 |
| Annual Expenditure Detail | 8 |
| Component Detail | 11 |
| Index | 26 |

Preface

This preface is intended to provide an introduction to the enclosed reserve analysis as well as detailed information regarding the reserve analysis report format, reserve fund goals/objectives and calculation methods. The following sections are included in this preface:

| | |
|--|-----------|
| Introduction to Reserve Budgeting | page i |
| Understanding the Reserve Analysis | page i |
| Reserve Funding Goals / Objectives | page ii |
| Reserve Funding Calculation Methods | page ii |
| Reading the Reserve Analysis | page v |
| Glossary of Key Terms | page x |
| Limitations of Reserve Analysis | page xiii |

◆ ◆ ◆ ◆ INTRODUCTION TO RESERVE BUDGETING ◆ ◆ ◆ ◆

The Board of Directors of an association has a legal and fiduciary duty to maintain the community in a good state of repair. Individual unit property values are significantly impacted by the level of maintenance and upkeep provided by the association as well as the amount of the regular assessment charged to each owner.

A prudent plan must be implemented to address the issues of long-range maintenance, repair and replacement of the common areas. Additionally, the plan should recognize that the value of each unit is affected by the amount of the regular assessment charged to each unit.

There is a fine line between “not enough,” “just right” and “too much.” Each member of an association should contribute to the reserve fund for their proportionate amount of “depreciation” (or “use”) of the reserve components. Through time, if each owner contributes his “fair share” into the reserve fund for the depreciation of the reserve components, then the possibility of large increases in regular assessments or special assessments will be minimized.

An accurate reserve analysis and a “healthy” reserve fund are essential to protect and maintain the association's common areas and the property values of the individual unit owners. A comprehensive reserve analysis is one of the most significant elements of any association's long-range plan and provides the critical link between sound business judgment and good fiscal planning. The reserve analysis provides a “financial blueprint” for the future of an association.

◆ ◆ ◆ ◆ UNDERSTANDING THE RESERVE ANALYSIS ◆ ◆ ◆ ◆

In order for the reserve analysis to be useful, it must be understandable by a variety of individuals. Board members (from seasoned, experienced Board members to new Board members), property managers, accountants, attorneys and even homeowners may ultimately review the reserve analysis. The reserve analysis must be detailed enough to provide a comprehensive analysis, yet simple enough to enable less experienced individuals to understand the results.

There are four key bits of information that a comprehensive reserve analysis should provide: Budget, Percent Funded, Projections and Inventory. This information is described as follows:

Budget

Amount recommended to be transferred into the reserve account for the fiscal year for which the reserve analysis was prepared. In some cases, the reserve analysis may present two or more funding plans based on different goals/objectives. The Board should have a clear understanding of the differences among these funding goals/objectives prior to implementing one of them in the annual budget.

Percent Funded

Measure of the reserve fund “health” (expressed as a percentage) as of the beginning of the fiscal year for which the

Preface

reserve analysis was prepared. This figure is the ratio of the actual reserve fund on hand to the fully funded balance. A reserve fund that is “100% funded” means the association has accumulated the proportionately correct amount of money, to date, for the reserve components it maintains.

Projections

Indicate the “level of service” the association will provide the membership as well as a “road map” for the fiscal future of the association. The projections define the timetables for repairs and replacements, such as when the buildings will be painted or when the asphalt will be seal coated. The projections also show the financial plan for the association – when an underfunded association will “catch up” or how a properly funded association will remain fiscally “healthy.”

Inventory

Complete listing of the reserve components. Key bits of information are available for each reserve component, including placed-in-service date, useful life, remaining life, replacement year, quantity, current cost of replacement, future cost of replacement and analyst’s comments.

◆ ◆ ◆ ◆ RESERVE FUNDING GOALS / OBJECTIVES ◆ ◆ ◆ ◆

There are four reserve funding goals/objectives which may be used to develop a reserve funding plan that corresponds with the risk tolerance of the association: Full Funding, Baseline Funding, Threshold Funding and Statutory Funding. These goals/objectives are described as follows:

Full Funding

Describes the goal/objective to have reserves on hand equivalent to the value of the deterioration of each reserve component. The objective of this funding goal is to achieve and/or maintain a 100% percent funded reserve fund. The component calculation method or cash flow calculation method is typically used to develop a full funding plan.

Baseline Funding

Describes the goal/objective to have sufficient reserves on hand to never completely run out of money. The objective of this funding goal is to simply pay for all reserve expenses as they come due without regard to the association’s percent funded. The cash flow calculation method is typically used to develop a baseline funding plan.

Threshold Funding

Describes the goal/objective other than the 100% level (full funding) or just staying cash-positive (baseline funding). This threshold goal/objective may be a specific percent funded target or a cash balance target. Threshold funding is often a value chosen between full funding and baseline funding. The cash flow calculation method is typically used to develop a threshold funding plan.

Statutory Funding

Describes the pursuit of an objective as described or required by local laws or codes. The component calculation method or cash flow calculation method is typically used to develop a statutory funding plan.

◆ ◆ ◆ ◆ RESERVE FUNDING CALCULATION METHODS ◆ ◆ ◆ ◆

There are two funding methods which can be used to develop a reserve funding plan based on a reserve funding goal/objective: Component Calculation Method and Cash Flow Calculation Method. These calculation methods are described as follows:

Component Calculation Method

This calculation method develops a funding plan for each individual reserve component. The sum of the funding plan for each component equals the total funding plan for the association. This method is often referred to as the “straight line”

Preface

method and is widely believed to be the most conservative reserve funding method. This method structures a funding plan that enables the association to pay all reserve expenditures as they come due, enables the association to achieve the ideal level of reserves in time, and then enables the association to maintain the ideal level of reserves through time. The following is a detailed description of the component calculation method:

Step 1: Calculation of fully funded balance for each component

The fully funded balance is calculated for each component based on its age, useful life and current cost. The actual formula is as follows:

$$\text{Fully Funded Balance} = \frac{\text{Age}}{\text{Useful Life}} \times \text{Current Cost}$$

Step 2: Distribution of current reserve funds

The association's current reserve funds are assigned to (or distributed amongst) the reserve components based on each component's remaining life and fully funded balance as follows:

Pass 1: Components are organized in remaining life order, from least to greatest, and the current reserve funds are assigned to each component up to its fully funded balance, until reserves are exhausted.

Pass 2: If all components are assigned their fully funded balance and additional funds exist, they are assigned in a "second pass." Again, the components are organized in remaining life order, from least to greatest, and the remaining current reserve funds are assigned to each component up to its current cost, until reserves are exhausted.

Pass 3: If all components are assigned their current cost and additional funds exist, they are assigned in a "third pass." Components with a remaining life of zero years are assigned double their current cost.

Distributing, or assigning, the current reserve funds in this manner is the most efficient use of the funds on hand – it defers the make-up period of any underfunded reserves over the lives of the components with the largest remaining lives.

Step 3: Developing a funding plan

After step 2, all components have a "starting" balance. A calculation is made to determine what funding would be required to get from the starting balance to the future cost over the number of years remaining until replacement. The funding plan incorporates the annual contribution increase parameter to develop a "stair stepped" contribution.

For example, if an association needs to accumulate \$100,000 in ten years, \$10,000 could be contributed each year. Alternatively, the association could contribute \$8,723 in the first year and increase the contribution by 3% each year thereafter until the tenth year.

In most cases, this rate should match the inflation parameter. Matching the annual contribution increase parameter to the inflation parameter indicates, in theory, that member contributions should increase at the same rate as the cost of living (inflation parameter). Due to the "time value of money," this creates the most equitable distribution of member contributions through time.

Using an annual contribution increase parameter that is greater than the inflation parameter will reduce the burden to the current membership at the expense of the future membership. Using an annual contribution increase parameter that is less than the inflation parameter will increase the burden to the current membership to the benefit of the future membership. The following chart shows a comparison:

Preface

| | <u>0% Increase</u> | <u>3% Increase</u> | <u>10% Increase</u> |
|---------|--------------------|--------------------|---------------------|
| Year 1 | \$10,000.00 | \$8,723.05 | \$6,274.54 |
| Year 2 | \$10,000.00 | \$8,984.74 | \$6,901.99 |
| Year 3 | \$10,000.00 | \$9,254.28 | \$7,592.19 |
| Year 4 | \$10,000.00 | \$9,531.91 | \$8,351.41 |
| Year 5 | \$10,000.00 | \$9,817.87 | \$9,186.55 |
| Year 6 | \$10,000.00 | \$10,112.41 | \$10,105.21 |
| Year 7 | \$10,000.00 | \$10,415.78 | \$11,115.73 |
| Year 8 | \$10,000.00 | \$10,728.25 | \$12,227.30 |
| Year 9 | \$10,000.00 | \$11,050.10 | \$13,450.03 |
| Year 10 | \$10,000.00 | \$11,381.60 | \$14,795.04 |
| TOTAL | \$100,000.00 | \$100,000.00 | \$100,000.00 |

This parameter is used to develop a funding plan only; it does not necessarily mean that the reserve contributions must be raised each year. There are far more significant factors that will contribute to a total reserve contribution increase or decrease from year to year than this parameter.

One of the major benefits of using this calculation method is that for any single component (or group of components), the accumulated balance and reserve funding can be precisely calculated. For example, using this calculation method, the reserve analysis can indicate the exact amount of current reserve funds “in the bank” for the roofs and the amount of money being funded towards the roofs each month. This information is displayed on the Management / Accounting Summary and Charts as well as elsewhere within the report.

Cash Flow Calculation Method

This calculation method develops a funding plan based on current reserve funds and projected expenditures during a specific timeframe (typically 30 years). This funding method structures a funding plan that enables the association to pay for all reserve expenditures as they come due, but is not necessarily concerned with the ideal level of reserves through time.

This calculation method tests reserve contributions against reserve expenditures through time to determine the minimum contribution necessary (baseline funding) or some other defined goal/objective (full funding, threshold funding or statutory funding). Unlike the component calculation method, this calculation method cannot precisely calculate the reserve funding for any single component (or group of components). In order to work-around this issue to provide this bookkeeping information, a formula has been applied to component method results to calculate a reasonable breakdown. This information is displayed on the Management / Accounting Summary and Charts as well as elsewhere within the report.

The **Directed Cash Flow Calculation Method** is our primary calculation method. It allows for several funding strategies to be manually tested until the optimal funding strategy accomplishing three goals is created:

Goal #1: Ensures that all scheduled reserve expenditures are covered by keeping the reserve cash balance above zero during the projected period (typically 30 years)

Goal #2: Uniformly distributes the costs of replacements over time to benefit both current & future members of the association by using consistent, incremental contribution increases

Goal #3: Provides for the lowest reserve funding recommendation as possible over time with the goal of approaching, reaching and/or maintaining a 100% fully funded reserve balance

These very important aspects of the **Directed Cash Flow Calculation Method** will greatly aid the board of directors during the annual budgeting process.

Preface

◆ ◆ ◆ ◆ READING THE RESERVE ANALYSIS ◆ ◆ ◆ ◆

In some cases, the reserve analysis may be a lengthy document of one hundred pages or more. A complete and thorough review of the reserve analysis is always a good idea. However, if time is limited, it is suggested that a thorough review of the summary pages be made. If a “red flag” is raised in this review, the reader should then check the detail information, of the component in question, for all relevant information. In this section, a description of most of the summary or report sections is provided along with comments regarding what to look for and how to use each section.

Executive Summary

Provides general information about the client, global parameters used in the calculation of the reserve analysis as well as the core results of the reserve analysis.

Client Information

Provides various client information including fiscal year for which the reserve analysis was prepared, number of units, phasing, etc.

Global Parameters

Displays the calculation parameters that were used to calculate the reserve analysis including inflation, annual contribution increase, investment rate, tax rate and contingency.

Community Profile

Provides brief description of the community, as well as other “global” type comments.

Budget

Provides recommended funding for the fiscal year for which the reserve analysis was prepared. Indicates the reserve funding from the membership, anticipated interest contribution and the total contribution

| Sample Homeowners Association Executive Summary Component Calculation Method | | | |
|---|-----------------------|------------------------------|-----------------------|
| Client Information: | | Global Parameters: | |
| Account Number | 99999 | Inflation Rate | 2.00% |
| Version Number | 1 | Annual Contribution Increase | 2.00% |
| Analysis Date | 3/18/2014 | Investment Rate | 1.00% |
| Fiscal Year | 6/1/2014 to 5/31/2015 | Taxes on Investments | 30.00% |
| Number of Units | 187 | Contingency | 3.00% |
| Phasing | 8 of 8 | | |
| Community Profile: | | | |
| This community consists of 187 attached units with private roadways, pool area and extensive landscaped areas. | | | |
| For budgeting purposes, unless otherwise indicated, we have used June 1995 as the average placed-in-service date for aging the original components in this community. | | | |
| ARS site visits: March 1, 2014; January 2011; February 2008; April 2008; March 2005; March 2003; March 2002; April 2001 and March 2000 | | | |
| Adequacy of Reserves as of June 1, 2014: | | | |
| Anticipated Reserve Balance | | \$865,450.00 | |
| Fully Funded Reserve Balance | | \$1,011,228.83 | |
| Percent Funded | | 85.58% | |
| Recommended Funding for the 2014-2015 Fiscal Year: | | | |
| | Annual | Monthly | Per Unit Per Month |
| Member Contribution | \$110,659 | \$9,221.58 | \$55.22 |
| Interest Contribution | \$5,977 | \$498.09 | \$2.98 |
| Total Contribution | \$116,636 | \$9,719.66 | \$58.20 |
| 3.18.2014(1) 1 ADVANCED RESERVE SOLUTIONS, INC. | | | |

Adequacy of Reserves

Displays the results of calculations with regard to the “health” of the reserve fund as of the beginning of the fiscal year for which the reserve analysis was prepared. Provides the anticipated reserve balance, fully funded reserve balance and the percent funded.

Preface

Calculation of Percent Funded

Summary displays all reserve components, shown here in “category” order. Provides the remaining life, useful life, current cost and the fully funded balance at the beginning of the fiscal year for which the reserve analysis was prepared.

Reserve Components
All components are displayed (shown here in “category” order).

Lifespans
Remaining life and useful life are displayed. And, these columns are conveniently sub totaled to show range.

Sample Homeowners Association
Calculation of Percent Funded
Sorted by Category

| | Remaining Life | Useful Life | Current Cost | Fully Funded Balance |
|--|----------------|-------------|---------------------|----------------------|
| 010 Streets | | | | |
| Streets - Asphalt, Overlay / Major Rehab | 8 | 27 | \$101,697.50 | \$71,564.91 |
| Streets - Asphalt, Repair | 0 | 4 | \$3,621.75 | \$3,621.75 |
| Streets - Asphalt, Seal Coat | 0 | 4 | \$5,926.50 | \$5,926.50 |
| Streets - Concrete, Unfunded | n.a. | n.a. | \$0.00 | \$0.00 |
| Sub Total | 0-8 | 4-27 | \$111,245.75 | \$81,113.16 |
| 020 Roofs | | | | |
| Roofs - Tile | | | | |
| Sub Total | | | | |
| 030 Painting | | | | |
| Painting - Cabana Interior | | | | |
| Painting - Red Curbs | | | | |
| Painting - Stucco | | | | |
| Painting - Woodwork & Trim | | | | |
| Painting - Wrought Iron, Buildings | | | | |
| Painting - Wrought Iron, Pool Area | | | | |
| Sub Total | | | | |
| 040 Fencing | | | | |
| Fencing - Wrought Iron, Pool Area | | | | |
| Railing - Wrought Iron, Buildings | | | | |
| Sub Total | | | | |
| 050 Lighting | | | | |
| Lighting - Buildings | | | | |
| Lighting - Grounds | | | | |
| Sub Total | | | | |
| 060 Pool Area | | | | |
| Cabana - Ceramic Tile | | | | |
| Cabana - Doors | | | | |
| Cabana - Plumbing Fixtures | | | | |
| Cabana - Restroom Partitions | | | | |
| Cabana - Water Heater | | | | |
| Pool - Filter | | | | |
| Pool - Heater | | | | |
| Pool - Replaster & Tile Replace | | | | |
| Pool Area - Barbecues | | | | |
| Sub Total | | | | |

Sample Homeowners Association
Calculation of Percent Funded
Sorted by Category

| | Remaining Life | Useful Life | Current Cost | Fully Funded Balance |
|-------------------------------------|----------------|--------------|-----------------------|-----------------------|
| Pool Area - Ceramic Tile | 2 | 21 | \$8,591.63 | \$7,773.38 |
| Pool Area - Concrete Deck, Unfunded | n.a. | n.a. | \$0.00 | \$0.00 |
| Pool Area - Furniture (Refurbish) | 0 | 12 | \$9,255.00 | \$9,255.00 |
| Pool Area - Furniture (Replace) | 6 | 25 | \$17,315.00 | \$13,159.40 |
| Pool Area - Mastic | 0 | 4 | \$5,131.50 | \$5,131.50 |
| Spa - Filter | 0 | 13 | \$1,350.00 | \$1,350.00 |
| Spa - Heater | 0 | 10 | \$3,050.00 | \$3,050.00 |
| Spa - Replaster & Tile Replace | 3 | 8 | \$5,250.00 | \$3,126.40 |
| Sub Total | 0-6 | 4-25 | \$91,747.38 | \$71,964.53 |
| 070 Decks | | | | |
| Decks - Clean & Top Coat | 2 | 5 | \$30,480.00 | \$18,288.00 |
| Decks - Resurface | 2 | 13 | \$65,227.20 | \$54,720.81 |
| Sub Total | 2 | 5-13 | \$95,707.20 | \$73,008.81 |
| 080 Misc (Buildings) | | | | |
| Fire Extinguisher Cabinets | 2 | 21 | \$27,625.00 | \$24,904.05 |
| Utility Closet Doors | 2 | 21 | \$73,900.00 | \$68,881.90 |
| Sub Total | 2 | 21 | \$101,525.00 | \$91,855.95 |
| 090 Misc (Grounds) | | | | |
| Landscape - Irrigation Controllers | 0 | 12 | \$28,000.00 | \$29,000.00 |
| Landscape - Renovation, Unfunded | n.a. | n.a. | \$0.00 | \$0.00 |
| Mailboxes | 2 | 21 | \$37,200.00 | \$32,657.14 |
| Sub Total | 0-2 | 12-21 | \$66,200.00 | \$62,657.14 |
| 100 Termite Control | | | | |
| Termite Control | n.a. | n.a. | \$0.00 | \$100,000.00 |
| Sub Total | n.a. | n.a. | \$0.00 | \$100,000.00 |
| Contingency | n.a. | n.a. | n.a. | \$29,453.27 |
| Total | 0-11 | 2-30 | \$1,091,533.70 | \$1,011,228.83 |
| Anticipated Reserve Balance | | | | \$865,450.00 |
| Percent Funded | | | | 85.58% |

Current Cost
Displays the current cost to replace or otherwise maintain each component. This column is conveniently sub totaled.

Fully Funded Balance
Displays the fully funded balance for each component. This column is conveniently sub totaled.

The total current cost to replace or otherwise maintain all components, total fully funded balance, anticipated reserve balance and percent funded are provided at the bottom of this summary. Also shown is the range of reserve component remaining lives and useful lives.

Preface

Management / Accounting Summary and Charts

Summary displays all reserve components, shown here in “category” order. Provides the assigned reserve funds at the beginning of the fiscal year for which the reserve analysis was prepared along with the monthly member contribution, interest contribution and total contribution for each component and category. Pie charts show graphically how the total reserve fund is distributed amongst the reserve component categories and how each category is funded on a monthly basis.

Balance at FYB
Shows the amount of reserve funds assigned to each reserve component. And, this column is conveniently sub totaled.


Sample Homeowners Association
Management / Accounting Summary
Component Calculation Method; Sorted by Category

| | Balance at Fiscal Year Beginning | Monthly Member Contribution | Monthly Interest Contribution | Total Monthly Contribution |
|--|----------------------------------|-----------------------------|-------------------------------|----------------------------|
| 010 Streets | | | | |
| Streets - Asphalt, Overlay / Major Rehab | \$17,837.90 | \$948.09 | \$13.37 | \$963.07 |
| Streets - Asphalt, Repair | \$3,621.75 | \$78.20 | \$0.25 | \$78.45 |
| Streets - Asphalt, Seal Coat | \$5,028.50 | \$127.96 | \$0.41 | \$128.37 |
| Streets - Concrete, Unfunded | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| Sub Total | \$27,186.15 | \$1,155.84 | \$14.04 | \$1,169.88 |
| 020 Roofs | | | | |
| Roofs - Tile | | | | |
| Sub Total | | | | |
| 030 Painting | | | | |
| Painting - Cabana Interior | | | | |
| Painting - Red Curbs | | | | |
| Painting - Stucco | | | | |
| Painting - Woodwork & Trim | | | | |
| Painting - Wrought Iron, Buildings | | | | |
| Painting - Wrought Iron, Pool Area | | | | |
| Sub Total | | | | |
| 040 Fencing | | | | |
| Fencing - Wrought Iron, Pool Area | | | | |
| Railing - Wrought Iron, Buildings | | | | |
| Sub Total | | | | |
| 050 Lighting | | | | |
| Lighting - Buildings | | | | |
| Lighting - Grounds | | | | |
| Sub Total | | | | |
| 060 Pool Area | | | | |
| Cabana - Ceramic Tile | | | | |
| Cabana - Doors | | | | |
| Cabana - Plumbing Fixtures | | | | |
| Cabana - Restroom Partitions | | | | |
| Cabana - Water Heater | | | | |
| Pool - Filter | | | | |
| Sub Total | | | | |


Sample Homeowners Association
Management / Accounting Summary
Component Calculation Method; Sorted by Category

| | Balance at Fiscal Year Beginning | Monthly Member Contribution | Monthly Interest Contribution | Total Monthly Contribution |
|-------------------------------------|----------------------------------|-----------------------------|-------------------------------|----------------------------|
| Pool - Heater | \$3,250.00 | \$24.00 | \$0.08 | \$24.98 |
| Pool - Replaster & Tile Replace | \$7,070.58 | \$146.76 | \$4.01 | \$151.37 |
| Pool Area - Barbecues | \$1,010.00 | \$28.98 | \$0.09 | \$30.67 |
| Pool Area - Ceramic Tile | \$7,773.38 | \$43.27 | \$4.09 | \$47.95 |
| Pool Area - Concrete Deck, Unfunded | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| Pool Area - Furniture (Refurbish) | \$8,255.00 | \$70.05 | \$0.23 | \$70.27 |
| Pool Area - Furniture (Replace) | \$13,159.40 | \$74.76 | \$7.94 | \$82.70 |
| Pool Area - Mastic | \$5,131.50 | \$110.79 | \$0.36 | \$111.15 |
| Spa - Filter | \$1,350.00 | \$12.11 | \$0.04 | \$12.15 |
| Spa - Heater | \$2,000.00 | \$27.38 | \$0.09 | \$27.44 |
| Spa - Replaster & Tile Replace | \$3,128.40 | \$64.12 | \$2.04 | \$66.15 |
| Sub Total | \$71,964.53 | \$710.19 | \$30.10 | \$740.28 |
| 070 Decks | | | | |
| Decks - Clean & Top Coat | \$18,288.00 | \$539.52 | \$12.44 | \$551.96 |
| Decks - Resurfacing | \$54,720.81 | \$506.93 | \$33.85 | \$540.58 |
| Sub Total | \$73,008.81 | \$1,046.45 | \$46.09 | \$1,092.54 |
| 080 Misc (Buildings) | | | | |
| Fire Extinguisher Cabinets | \$24,994.05 | \$139.11 | \$15.07 | \$154.19 |
| Utility Closet Doors | \$66,861.80 | \$372.15 | \$40.32 | \$412.47 |
| Sub Total | \$91,855.95 | \$511.26 | \$55.40 | \$566.66 |
| 090 Misc (Grounds) | | | | |
| Landscape - Irrigation Controllers | \$28,000.00 | \$219.48 | \$0.71 | \$220.19 |
| Landscape - Renovation, Unfunded | \$0.00 | \$0.00 | \$0.00 | \$0.00 |
| Mailboxes | \$33,657.14 | \$187.33 | \$20.30 | \$207.63 |
| Sub Total | \$62,657.14 | \$406.82 | \$21.00 | \$427.82 |
| 100 Termite Control | | | | |
| Termite Control | \$100,000.00 | \$0.00 | \$58.52 | \$58.52 |
| Sub Total | \$100,000.00 | \$0.00 | \$58.52 | \$58.52 |
| Contingency | \$25,207.28 | \$268.59 | \$15.61 | \$284.20 |
| Total | \$865,450.00 | \$9,221.58 | \$498.09 | \$9,719.66 |

Monthly Funding
Displays the monthly funding for each component from the members and interest. Total monthly funding is also indicated. And, these columns are conveniently sub totaled.



Pie Charts
Show graphically how the reserve fund is distributed amongst the reserve components and how the components are funded.



Preface

Projections and Charts

Summary displays projections of beginning reserve balance, member contribution, interest contribution, expenditures and ending reserve balance for each year of the projection period (shown here for 30 years). The two columns on the right-hand side provide the fully funded ending balance and the percent funded for each year. Charts show the same information in an easy-to-understand graphic format.




**Sample Homeowners Association
Projections**
Component Calculation Method

| Fiscal Year | Beginning Balance | Member Contribution | Interest Contribution | Expenditures | Ending Balance | Fully Funded Ending Balance | Percent Funded |
|-------------|-------------------|---------------------|-----------------------|--------------|----------------|-----------------------------|----------------|
| 2014-2015 | \$865,450 | \$110,659 | \$5,977 | \$54,980 | \$917,106 | \$1,046,139 | 88% |
| 2015-2016 | \$917,106 | \$111,857 | \$6,482 | \$45,317 | \$990,127 | \$1,104,068 | 90% |
| 2016-2017 | \$990,127 | \$118,806 | \$3,175 | \$591,549 | \$518,559 | \$568,939 | 87% |
| 2017-2018 | \$518,559 | \$115,807 | \$3,960 | \$7,715 | \$630,610 | \$668,915 | 79% |
| 2018-2019 | \$630,610 | \$116,508 | \$4,431 | \$52,973 | \$998,577 | \$755,512 | 94% |
| 2019-2020 | \$998,577 | \$116,723 | \$5,037 | \$34,701 | \$785,576 | \$834,243 | 94% |
| 2020-2021 | \$785,576 | \$118,645 | \$5,331 | \$80,731 | \$528,821 | \$686,179 | 95% |
| 2021-2022 | \$528,821 | \$121,026 | \$5,925 | \$40,530 | \$915,241 | \$948,147 | 96% |
| 2022-2023 | \$915,241 | \$123,506 | | | | | |
| 2023-2024 | \$907,080 | \$125,898 | | | | | |
| 2024-2025 | \$1,037,322 | \$128,436 | | | | | |
| 2025-2026 | \$825,894 | \$127,755 | | | | | |
| 2026-2027 | \$780,089 | \$125,648 | | | | | |
| 2027-2028 | \$713,358 | \$119,373 | | | | | |
| 2028-2029 | \$631,867 | \$131,699 | | | | | |
| 2029-2030 | \$698,194 | \$131,038 | | | | | |
| 2030-2031 | \$1,013,798 | \$137,575 | | | | | |
| 2031-2032 | \$1,130,618 | \$141,510 | | | | | |
| 2032-2033 | \$1,237,543 | \$143,182 | | | | | |
| 2033-2034 | \$973,396 | \$138,581 | | | | | |
| 2034-2035 | \$1,104,489 | \$147,134 | | | | | |
| 2035-2036 | \$1,222,996 | \$149,242 | | | | | |
| 2036-2037 | \$1,317,743 | \$155,808 | | | | | |
| 2037-2038 | \$929,828 | \$142,179 | | | | | |
| 2038-2039 | \$1,078,962 | \$157,613 | | | | | |
| 2039-2040 | \$1,102,377 | \$157,111 | | | | | |
| 2040-2041 | \$1,234,892 | \$165,390 | | | | | |
| 2041-2042 | \$852,393 | \$161,588 | | | | | |
| 2042-2043 | \$1,056,301 | \$171,747 | | | | | |
| 2043-2044 | \$1,200,105 | \$169,289 | | | | | |

NOTE: In some cases, the projected Ending Balance Expenditures. This is a result of the provision of contingency is continually adjusted according to

Improved format makes the numbers as easy to read and understand as possible. The color-coded bar indicates the reserve fund status:

Green: Good
Yellow: Fair
Red: Poor



Charts
Show graphically the reserve funding plan through time.

Preface

Component Detail

Summary provides detailed information about each reserve component. These pages display all information about each reserve component as well as comments from site observations and historical information regarding replacement or other maintenance.

Lifespan Information
Displays placed-in-service date, useful life, remaining life and replacement year.

Cost Information
Displays quantity, unit cost, percentage of replacement, current cost and future cost.

Calculation Results
Displays assigned reserves and funding requirements.

Comments
Useful information from site observations and historical expenses included here.

Photos
Optional inclusion of photos adds an additional layer of detail to the reserve analysis.

Preface

◆ ◆ ◆ ◆ GLOSSARY OF KEY TERMS ◆ ◆ ◆ ◆

Annual Contribution Increase Parameter

The rate used in the calculation of the funding plan. This rate is used on an annual compounding basis. This rate represents, in theory, the rate the association expects to increase contributions each year.

In most cases, this rate should match the inflation parameter. Matching the annual contribution increase parameter to the inflation parameter indicates, in theory, that member contributions should increase at the same rate as the cost of living (inflation parameter). Due to the “time value of money,” this creates the most equitable distribution of member contributions through time.

This parameter is used to develop a funding plan only; it does not necessarily mean that the reserve contributions must be raised each year. There are far more significant factors that will contribute to a total reserve contribution increase or decrease from year to year than this parameter. See the description of “reserve funding calculation methods” in this preface for more detail on this parameter.

Anticipated Reserve Balance (or Reserve Funds)

The amount of money, as of a certain point in time, held by the association to be used for the repair or replacement of reserve components. This figure is “anticipated” because it is calculated based on the most current financial information available as of the analysis date, which is almost always prior to the fiscal year beginning date for which the reserve analysis is prepared.

Assigned Funds (and “Fixed” Assigned Funds)

The amount of money, as of the fiscal year beginning date for which the reserve analysis is prepared, that a reserve component has been assigned.

The assigned funds are considered “fixed” when the normal calculation process is bypassed and a specific amount of money is assigned to a reserve component. For example, if the normal calculation process assigns \$10,000 to the roofs, but the association would like to show \$20,000 assigned to roofs, “fixed” funds of \$20,000 can be assigned.

Cash Flow Calculation Method

Reserve funding calculation method developed based on total annual expenditures. A more detailed description of the actual calculation process is included in the “reserve funding calculation methods” section of the preface.

Component Calculation Method

Reserve funding calculation method developed based on each individual component. A more detailed description of the actual calculation process is included in the “reserve funding calculation methods” section of the preface.

Contingency Parameter

The rate used as a built-in buffer in the calculation of the funding plan. This rate will assign a percentage of the reserve funds, as of the fiscal year beginning, as contingency funds and will also determine the level of funding toward the contingency each month.

Current Replacement Cost

The amount of money, as of the fiscal year beginning date for which the reserve analysis is prepared, that a reserve component is expected to cost to replace.

Fiscal Year

Indicates the budget year for the association for which the reserve analysis was prepared. The fiscal year beginning (FYB) is the first day of the budget year; the fiscal year end (FYE) is the last day of the budget year.

Fully Funded Reserve Balance (or Ideal Reserves)

The amount of money that should theoretically have accumulated in the reserve fund as of a certain point in time. Fully funded reserves are calculated for each reserve component based on the current replacement cost, age and useful life.

Preface

$$\text{Fully Funded Reserves} = \frac{\text{Age}}{\text{Useful Life}} \times \text{Current Replacement Cost}$$

The fully funded reserve balance is the sum of the fully funded reserves for each reserve component.

An association that has accumulated the fully funded reserve balance does not have all of the funds necessary to replace all of its reserve components immediately; it has the proportionately appropriate reserve funds for the reserve components it maintains, based on each component's current replacement cost, age and useful life.

Future Replacement Cost

The amount of money, as of the fiscal year during which replacement of a reserve component is scheduled, that a reserve component is expected to cost to replace. This cost is calculated using the current replacement cost compounded annually by the inflation parameter.

Global Parameters

The financial parameters used to calculate the reserve analysis. See also "inflation parameter," "annual contribution increase parameter," "investment rate parameter" and "taxes on investments parameter."

Inflation Parameter

The rate used in the calculation of future costs for reserve components. This rate is used on an annual compounding basis. This rate represents the rate the association expects the cost of goods and services relating to their reserve components to increase each year.

Interest Contribution

The amount of money contributed to the reserve fund by the interest earned on the reserve fund and member contributions.

Investment Rate Parameter

The gross rate used in the calculation of interest contribution (interest earned) from the reserve balance and member contributions. This rate (net of the taxes on investments parameter) is used on a monthly compounding basis. This parameter represents the weighted average interest rate the association expects to earn on their reserve fund investments.

Membership Contribution

The amount of money contributed to the reserve fund by the association's membership.

Monthly Contribution (and "Fixed" Monthly Contribution)

The amount of money, for the fiscal year which the reserve analysis is prepared, that a reserve component will be funded.

The monthly contribution is considered "fixed" when the normal calculation process is bypassed and a specific amount of money is funded to a reserve component. For example, if the normal calculation process funds \$1,000 to the roofs each month, but the association would like to show \$500 funded to roofs each month, a "fixed" contribution of \$500 can be assigned.

Number of Units (or other assessment basis)

Indicates the number of units for which the reserve analysis was prepared. In "phased" developments (see phasing), this number represents the number of units, and corresponding common area components, that existed as of a certain point in time.

For some associations, assessments and reserve contributions are based on a unit of measure other than the number of units. Examples include time-interval weeks for timeshare resorts or lot acreage for commercial/industrial developments.

Preface

One-Time Replacement

Used for components that will be budgeted for only once.

Percent Funded

A measure, expressed as a percentage, of the association's reserve fund "health" as of a certain point in time. This number is the ratio of the anticipated reserve fund balance to the fully funded reserve balance:

$$\text{Percent Funded} = \frac{\text{Anticipated Reserve Fund Balance}}{\text{Fully Funded Reserve Balance}}$$

An association that is 100% funded does not have all of the reserve funds necessary to replace all of its reserve components immediately; it has the proportionately appropriate reserve funds for the reserve components it maintains, based on each component's current replacement cost, age and useful life.

Percentage of Replacement

The percentage of the reserve component that is expected to be replaced.

For most reserve components, this percentage should be 100%. In some cases, this percentage may be more or less than 100%. For example, fencing which is shared with a neighboring community may be set at 50%.

Phasing

Indicates the number of phases for which the reserve analysis was prepared and the total number of phases expected at build-out (i.e. Phase 4 of 7). In phased developments, the first number represents the number of phases, and corresponding common area components, that existed as of a certain point in time. The second number represents the number of phases that are expected to exist at build-out.

Placed-In-Service Date

The date (month and year) that the reserve component was originally put into service or last replaced.

Remaining Life

The length of time, in years, until a reserve component is scheduled to be replaced.

Remaining Life Adjustment

The length of time, in years, that a reserve component is expected to last in excess (or deficiency) of its useful life for the current cycle of replacement.

If the current cycle of replacement for a reserve component is expected to be greater than or less than the "normal" life expectancy, the reserve component's life should be adjusted using a remaining life adjustment.

For example, if wood trim is painted normally on a 4 year cycle, the useful life should be 4 years. However, when it comes time to paint the wood trim and it is determined that it can be deferred for an additional year, the useful life should remain at 4 years and a remaining life adjustment of +1 year should be used.

Replacement Year

The fiscal year that a reserve component is scheduled to be replaced.

Reserve Components

Line items included in the reserve analysis.

Taxes on Investments Parameter

The rate used to offset the investment rate parameter in the calculation of the interest contribution. This parameter represents the marginal tax rate the association expects to pay on interest earned by the reserve funds and member contributions.

Preface

Total Contribution

The sum of the membership contribution and interest contribution.

Useful Life

The length of time, in years, that a reserve component is expected to last each time it is replaced. See also “remaining life adjustment.”

◆ ◆ ◆ ◆ LIMITATIONS OF RESERVE ANALYSIS ◆ ◆ ◆ ◆

This reserve analysis is intended as a tool for the association’s Board of Directors to be used in evaluating the association’s current physical and financial condition with regard to reserve components. The results of this reserve analysis represent the independent opinion of the preparer. There is no implied warranty or guarantee of this work product.

For the purposes of this reserve analysis, it has been assumed that all components have been installed properly, no construction defects exist and all components are operational. Additionally, it has been assumed that all components will be maintained properly in the future.

The representations set forth in this reserve analysis are based on the best information and estimates of the preparer as of the date of this analysis. These estimates are subject to change. This reserve analysis includes estimates of replacement costs and life expectancies as well as assumptions regarding future events. Some estimates are projections of future events based on information currently available and are not necessarily indicative of the actual future outcome. The longer the time period between the estimate and the estimated event, the more likely the possibility of error and/or discrepancy. For example, some assumptions inevitably will not materialize and unanticipated events and circumstances may occur subsequent to the preparation of this reserve analysis. Therefore, the actual replacement costs and remaining lives may vary from this reserve analysis and the variation may be significant. Additionally, inflation and other economic events may impact this reserve analysis, particularly over an extended period of time and those events could have a significant and negative impact on the accuracy of this reserve analysis and, further, the funds available to meet the association’s obligation for repair, replacement or other maintenance of major components during their estimated useful life. Furthermore, the occurrence of vandalism, severe weather conditions, earthquakes, floods, acts of nature or other unforeseen events cannot be predicted and/or accounted for and are excluded when assessing life expectancy, repair and/or replacement costs of the components.

Artesa

Executive Summary

Directed Cash Flow Calculation Method

Client Information:

| | |
|----------------|------------------------|
| Account Number | 3845 |
| Version Number | 003 |
| Analysis Date | 02/25/2022 |
| Fiscal Year | 1/1/2022 to 12/31/2022 |
| Number of Lots | 177 |
| Phasing | 1 of 1 |

Global Parameters:

| | |
|------------------------------|--------|
| Inflation Rate | 3.00 % |
| Annual Contribution Increase | 3.00 % |
| Investment Rate | 0.00 % |
| Taxes on Investments | 0.00 % |
| Contingency | 0.00 % |

Community Profile:

This community initially broke ground in 2007/2008 but construction ceased. Many of the reserve components were added throughout 2013, once development resumed. Refer to the Component Detail for the dates used to age the components examined in this analysis.

The January 1, 2022 reserve balance is \$93,230.98.

The client's 2022 budgeted reserve contribution is \$19,804.

REPORTS: 2014. Updated 2018 & 2022.

Adequacy of Reserves as of January 1, 2022:

| | |
|------------------------------|---------------------|
| Anticipated Reserve Balance | \$93,230.98 |
| Fully Funded Reserve Balance | \$174,869.14 |
| Percent Funded | 53.31% |

| Budgeted | Funding for the 2022 Fiscal Year: | Annual | Monthly | Per Lot Per Month |
|-----------------------|--|-----------------|-------------------|------------------------------|
| Member Contribution | | \$19,804 | \$1,650.33 | \$9.32 |
| Interest Contribution | | \$0 | \$0.00 | \$0.00 |
| Total Contribution | | \$19,804 | \$1,650.33 | \$9.32 |

Artesa

Distribution of Current Reserve Funds Sorted by Remaining Life

| | Remaining Life | Fully Funded Balance | Assigned Reserves |
|--|-------------------|----------------------------|----------------------|
| Grounds: Drywell Maintenance | 0 | \$3,000.00 | \$3,000.00 |
| Tract V: Tot Turf & Sand Removal (2022) | 0 | \$11,491.62 | \$11,491.62 |
| Lighting: SolarKing (Batteries) | 1 | \$750.00 | \$750.00 |
| Grounds: Mailboxes (Pedestal Sets) | 6 | \$17,360.00 | \$17,360.00 |
| Paint: Walls, Fencing, Monuments, Ramadas | 6 | \$5,142.86 | \$5,142.86 |
| Grounds: Granite Replenishment | 7 | \$70,000.00 | \$49,619.84 |
| Tract A: Park Equipment | 7 | \$2,400.00 | \$2,400.00 |
| Tract V: Park Equipment | 7 | \$3,466.67 | \$3,466.67 |
| Grounds: Irrigation Controllers | 10 | \$833.33 | \$0.00 |
| Lighting: SolarKing (Controllers & Lights) | 12 | \$500.00 | \$0.00 |
| Tract A: Playstructure | 12 | \$16,000.00 | \$0.00 |
| Tract A: Tot Turf | 12 | \$2,728.00 | \$0.00 |
| Tract V: Playstructure | 12 | \$16,000.00 | \$0.00 |
| Walls: Block (Repairs) | 16 | \$11,316.67 | \$0.00 |
| Fencing: Wrought Iron, Replace (100%) | 22 | \$9,100.00 | \$0.00 |
| Fencing: Wrought Iron, Replace (50%) | 22 | \$4,780.00 | \$0.00 |
| Fencing: Steel Split Rail (Unfunded) | n.a. | \$0.00 | \$0.00 |
| Grounds: Concrete Components (Unfunded) | n.a. | \$0.00 | \$0.00 |
| Grounds: Irrigation System (Unfunded) | n.a. | \$0.00 | \$0.00 |
| Grounds: Monument Sign Letters (Unfunded) | n.a. | \$0.00 | \$0.00 |
| Grounds: Tree Trimming (Unfunded) | n.a. | \$0.00 | \$0.00 |
| Roofs: Metal, Ramadas (Unfunded) | n.a. | \$0.00 | \$0.00 |
| Contingency | n.a. | \$0.00 | \$0.00 |
| Total | 0-22 | \$174,869.14 | \$93,230.98 |
| Percent Funded | | | 53.31% |

Artesa

Component Summary

Directed Cash Flow Calculation Method; Sorted by Category

| | Placed In Service Date | RL | UL | Inventory | Unit Cost | Current Cost | Theoretically Ideal Balance | Assigned Reserves | Monthly Member Contrib | Monthly Interest Contrib | Total Monthly Contrib |
|--|------------------------------|--------------|--------------|----------------|--------------|-----------------|--------------------------------|----------------------|------------------------------|--------------------------------|-----------------------------|
| 020 Roofs | | | | | | | | | | | |
| Roofs: Metal, Ramadas (Unfunded) | 1/2008 | n.a. | n.a. | 1 comment | \$0.00 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Sub Total | | | | | | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| 030 Painting | | | | | | | | | | | |
| Paint: Walls, Fencing, Monuments, Ramadas | 1/2021 | 6 | 7 | 1 total | \$36,000.00 | \$36,000 | \$5,143 | \$5,143 | \$245 | \$0 | \$245 |
| Sub Total | | 6 | 7 | | | \$36,000 | \$5,143 | \$5,143 | \$245 | \$0 | \$245 |
| 040 Fencing/Walls | | | | | | | | | | | |
| Fencing: Steel Split Rail (Unfunded) | 1/2008 | n.a. | n.a. | 1 comment | \$0.00 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Fencing: Wrought Iron, Replace (100%) | 1/2014 | 22 | 30 | 1 total | \$34,125.00 | \$34,125 | \$9,100 | \$0 | \$90 | \$0 | \$90 |
| Fencing: Wrought Iron, Replace (50%) | 1/2014 | 22 | 30 | 1 total | \$35,850.00 | \$17,925 | \$4,780 | \$0 | \$47 | \$0 | \$47 |
| Walls: Block (Repairs) | 1/2008 | 16 | 30 | 48,500 sq. ft. | \$25.00 | \$24,250 | \$11,317 | \$0 | \$81 | \$0 | \$81 |
| Sub Total | | 16-22 | 30 | | | \$76,300 | \$25,197 | \$0 | \$217 | \$0 | \$217 |
| 050 Lighting | | | | | | | | | | | |
| Lighting: SolarKing (Batteries) | 1/2019 | 1 | 4 | 1 total | \$1,000.00 | \$1,000 | \$750 | \$750 | \$12 | \$0 | \$12 |
| Lighting: SolarKing (Controllers & Lights) | 1/2019 | 12 | 15 | 1 total | \$2,500.00 | \$2,500 | \$500 | \$0 | \$11 | \$0 | \$11 |
| Sub Total | | 1-12 | 4-15 | | | \$3,500 | \$1,250 | \$750 | \$22 | \$0 | \$22 |
| 065 Parks | | | | | | | | | | | |
| Tract A: Park Equipment | 1/2014 | 7 | 15 | 1 total | \$4,500.00 | \$4,500 | \$2,400 | \$2,400 | \$17 | \$0 | \$17 |
| Tract A: Playstructure | 1/2014 | 12 | 20 | 1 total | \$40,000.00 | \$40,000 | \$16,000 | \$0 | \$168 | \$0 | \$168 |
| Tract A: Tot Turf | 1/2014 | 12 | 20 | 310 sq. ft. | \$22.00 | \$6,820 | \$2,728 | \$0 | \$29 | \$0 | \$29 |
| Tract V: Park Equipment | 1/2014 | 7 | 15 | 1 total | \$6,500.00 | \$6,500 | \$3,467 | \$3,467 | \$25 | \$0 | \$25 |
| Sub Total | | 7-12 | 15-20 | | | \$57,820 | \$24,595 | \$5,867 | \$239 | \$0 | \$239 |
| 066 Parks | | | | | | | | | | | |
| Tract V: Playstructure | 1/2014 | 12 | 20 | 1 total | \$40,000.00 | \$40,000 | \$16,000 | \$0 | \$168 | \$0 | \$168 |
| Tract V: Tot Turf & Sand Removal (2022) | 1/2014 | 0 | 8 | 1 total | \$11,491.62 | \$11,492 | \$11,492 | \$11,492 | \$0 | \$0 | \$0 |

Artesa

Component Summary

Directed Cash Flow Calculation Method; Sorted by Category

| | Placed In Service Date | RL | UL | Inventory | Unit Cost | Current Cost | Theoretically Ideal Balance | Assigned Reserves | Monthly Member Contrib | Monthly Interest Contrib | Total Monthly Contrib |
|---|------------------------------|-------------|-------------|------------|--------------|------------------|--------------------------------|----------------------|------------------------------|--------------------------------|-----------------------------|
| Sub Total | | 0-12 | 8-20 | | | \$51,492 | \$27,492 | \$11,492 | \$168 | \$0 | \$168 |
| 100 Grounds | | | | | | | | | | | |
| Grounds: Concrete Components (Unfunded) | 1/2008 | n.a. | n.a. | 1 comment | \$0.00 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Grounds: Drywell Maintenance | 1/2008 | 0 | 3 | 1 total | \$3,000.00 | \$3,000 | \$3,000 | \$3,000 | \$44 | \$0 | \$44 |
| Grounds: Granite Replenishment | 1/2014 | 7 | 15 | 1,750 tons | \$75.00 | \$131,250 | \$70,000 | \$49,620 | \$611 | \$0 | \$611 |
| Grounds: Irrigation Controllers | 1/2020 | 10 | 12 | 1 total | \$5,000.00 | \$5,000 | \$833 | \$0 | \$25 | \$0 | \$25 |
| Grounds: Irrigation System (Unfunded) | 1/2014 | n.a. | n.a. | 1 comment | \$0.00 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Grounds: Mailboxes (Pedestal Sets) | 1/2008 | 6 | 20 | 1 total | \$24,800.00 | \$24,800 | \$17,360 | \$17,360 | \$79 | \$0 | \$79 |
| Grounds: Monument Sign Letters (Unfunded) | 1/2008 | n.a. | n.a. | 1 comment | \$0.00 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Grounds: Tree Trimming (Unfunded) | 1/2008 | n.a. | n.a. | 1 comment | \$0.00 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Sub Total | | 0-10 | 3-20 | | | \$164,050 | \$91,193 | \$69,980 | \$759 | \$0 | \$759 |
| Contingency | | | | | | | \$0 | \$0 | \$0 | \$0 | \$0 |
| Total | | 0-22 | 3-30 | | | \$389,162 | \$174,869 | \$93,231 | \$1,650 | \$0 | \$1,650 |

NOTE: The dollar figures in this summary have been rounded to the nearest \$1.00. In some cases, the Sub Totals do not appear to "add up" due to a rounding error.

Artesa
Projections
Directed Cash Flow Calculation Method



| Fiscal Year | Beginning Balance | Member Contribution | Interest Contribution | Expenditures | Ending Balance | Fully Funded Ending Balance | Percent Funded |
|-------------|-------------------|---------------------|-----------------------|--------------|----------------|-----------------------------|----------------|
| 2022 | \$93,231 | \$19,804 | \$0 | \$14,492 | \$98,543 | \$190,510 | 52% |
| 2023 | \$98,543 | \$34,649 | \$0 | \$1,030 | \$132,163 | \$221,246 | 60% |
| 2024 | \$132,163 | \$35,689 | \$0 | \$0 | \$167,851 | \$254,746 | 66% |
| 2025 | \$167,851 | \$36,759 | \$0 | \$3,278 | \$201,332 | \$286,682 | 70% |
| 2026 | \$201,332 | \$37,862 | \$0 | \$0 | \$239,195 | \$323,782 | 74% |
| 2027 | \$239,195 | \$38,998 | \$0 | \$1,159 | \$277,033 | \$361,655 | 77% |
| 2028 | \$277,033 | \$40,168 | \$0 | \$76,181 | \$241,021 | \$324,274 | 74% |
| 2029 | \$241,021 | \$41,373 | \$0 | \$174,950 | \$107,444 | \$184,946 | 58% |
| 2030 | \$107,444 | \$42,614 | \$0 | \$0 | \$150,058 | \$222,571 | 67% |
| 2031 | \$150,058 | \$43,893 | \$0 | \$5,219 | \$188,732 | \$256,911 | 73% |
| 2032 | \$188,732 | \$45,209 | \$0 | \$6,720 | \$227,221 | \$291,727 | 78% |
| 2033 | \$227,221 | \$46,566 | \$0 | \$0 | \$273,787 | \$335,530 | 82% |
| 2034 | \$273,787 | \$47,963 | \$0 | \$131,626 | \$190,123 | \$246,123 | 77% |
| 2035 | \$190,123 | \$49,401 | \$0 | \$54,336 | \$185,189 | \$234,726 | 79% |
| 2036 | \$185,189 | \$50,884 | \$0 | \$0 | \$236,073 | \$280,069 | 84% |
| 2037 | \$236,073 | \$52,410 | \$0 | \$4,674 | \$283,809 | \$323,106 | 88% |
| 2038 | \$283,809 | \$53,982 | \$0 | \$38,914 | \$298,877 | \$336,024 | 89% |
| 2039 | \$298,877 | \$55,602 | \$0 | \$1,653 | \$352,826 | \$389,006 | 91% |
| 2040 | \$352,826 | \$57,270 | \$0 | \$5,107 | \$404,988 | \$441,359 | 92% |
| 2041 | \$404,988 | \$58,988 | \$0 | \$0 | \$463,976 | \$501,921 | 92% |
| 2042 | \$463,976 | \$60,758 | \$0 | \$65,020 | \$459,714 | \$498,748 | 92% |
| 2043 | \$459,714 | \$62,580 | \$0 | \$7,441 | \$514,853 | \$556,249 | 93% |
| 2044 | \$514,853 | \$64,458 | \$0 | \$381,879 | \$197,431 | \$231,310 | 85% |
| 2045 | \$197,431 | \$66,391 | \$0 | \$0 | \$263,823 | \$291,510 | 91% |
| 2046 | \$263,823 | \$68,383 | \$0 | \$6,098 | \$326,108 | \$348,832 | 93% |
| 2047 | \$326,108 | \$70,435 | \$0 | \$2,094 | \$394,449 | \$413,644 | 95% |
| 2048 | \$394,449 | \$72,548 | \$0 | \$105,781 | \$361,215 | \$375,298 | 96% |
| 2049 | \$361,215 | \$74,724 | \$0 | \$92,183 | \$343,756 | \$351,553 | 98% |
| 2050 | \$343,756 | \$76,966 | \$0 | \$0 | \$420,722 | \$423,843 | 99% |
| 2051 | \$420,722 | \$79,275 | \$0 | \$2,357 | \$497,640 | \$497,726 | 100% |

The Member Contribution column above reflects the client's 2022 budgeted reserve contribution of \$19,804. We recommend increasing the reserve contribution to \$34,649 in 2023, and then incorporating a 3.00% annual contribution increase going forward.

Artesa

Projection Charts



Directed Cash Flow Calculation Method



Artesa

Projection Charts

Directed Cash Flow Calculation Method



Artesa

Annual Expenditure Detail

Sorted by Description

| | | |
|---|--|---------------------|
| 2022 Fiscal Year | | |
| Grounds: Drywell Maintenance | | \$3,000.00 |
| Tract V: Tot Turf & Sand Removal (2022) | | \$11,491.62 |
| Sub Total | | \$14,491.62 |
| 2023 Fiscal Year | | |
| Lighting: SolarKing (Batteries) | | \$1,030.00 |
| Sub Total | | \$1,030.00 |
| 2025 Fiscal Year | | |
| Grounds: Drywell Maintenance | | \$3,278.18 |
| Sub Total | | \$3,278.18 |
| 2027 Fiscal Year | | |
| Lighting: SolarKing (Batteries) | | \$1,159.27 |
| Sub Total | | \$1,159.27 |
| 2028 Fiscal Year | | |
| Grounds: Drywell Maintenance | | \$3,582.16 |
| Grounds: Mailboxes (Pedestal Sets) | | \$29,612.50 |
| Paint: Walls, Fencing, Monuments, Ramadas | | \$42,985.88 |
| Sub Total | | \$76,180.54 |
| 2029 Fiscal Year | | |
| Grounds: Granite Replenishment | | \$161,420.94 |
| Tract A: Park Equipment | | \$5,534.43 |
| Tract V: Park Equipment | | \$7,994.18 |
| Sub Total | | \$174,949.56 |
| 2031 Fiscal Year | | |
| Grounds: Drywell Maintenance | | \$3,914.32 |
| Lighting: SolarKing (Batteries) | | \$1,304.77 |
| Sub Total | | \$5,219.09 |
| 2032 Fiscal Year | | |
| Grounds: Irrigation Controllers | | \$6,719.58 |
| Sub Total | | \$6,719.58 |
| 2034 Fiscal Year | | |
| Grounds: Drywell Maintenance | | \$4,277.28 |
| Lighting: SolarKing (Controlllers & Lights) | | \$3,564.40 |
| Tract A: Playstructure | | \$57,030.44 |

Artesa
Annual Expenditure Detail
Sorted by Description

| | |
|---|---------------------|
| Tract A: Tot Turf | \$9,723.69 |
| Tract V: Playstructure | \$57,030.44 |
| Sub Total | \$131,626.25 |
| | |
| 2035 Fiscal Year | |
| Lighting: SolarKing (Batteries) | \$1,468.53 |
| Paint: Walls, Fencing, Monuments, Ramadas | \$52,867.21 |
| Sub Total | \$54,335.75 |
| | |
| 2037 Fiscal Year | |
| Grounds: Drywell Maintenance | \$4,673.90 |
| Sub Total | \$4,673.90 |
| | |
| 2038 Fiscal Year | |
| Walls: Block (Repairs) | \$38,914.13 |
| Sub Total | \$38,914.13 |
| | |
| 2039 Fiscal Year | |
| Lighting: SolarKing (Batteries) | \$1,652.85 |
| Sub Total | \$1,652.85 |
| | |
| 2040 Fiscal Year | |
| Grounds: Drywell Maintenance | \$5,107.30 |
| Sub Total | \$5,107.30 |
| | |
| 2042 Fiscal Year | |
| Paint: Walls, Fencing, Monuments, Ramadas | \$65,020.00 |
| Sub Total | \$65,020.00 |
| | |
| 2043 Fiscal Year | |
| Grounds: Drywell Maintenance | \$5,580.88 |
| Lighting: SolarKing (Batteries) | \$1,860.29 |
| Sub Total | \$7,441.18 |
| | |
| 2044 Fiscal Year | |
| Fencing: Wrought Iron, Replace (100%) | \$65,387.03 |
| Fencing: Wrought Iron, Replace (50%) | \$34,346.15 |
| Grounds: Granite Replenishment | \$251,488.57 |
| Grounds: Irrigation Controllers | \$9,580.52 |
| Tract A: Park Equipment | \$8,622.47 |
| Tract V: Park Equipment | \$12,454.67 |

Artesa
Annual Expenditure Detail
Sorted by Description

| | |
|--|---------------------|
| Sub Total | \$381,879.41 |
| | |
| 2046 Fiscal Year | |
| Grounds: Drywell Maintenance | \$6,098.38 |
| Sub Total | \$6,098.38 |
| | |
| 2047 Fiscal Year | |
| Lighting: SolarKing (Batteries) | \$2,093.78 |
| Sub Total | \$2,093.78 |
| | |
| 2048 Fiscal Year | |
| Grounds: Mailboxes (Pedestal Sets) | \$53,483.46 |
| Walls: Block (Repairs) | \$52,297.34 |
| Sub Total | \$105,780.80 |
| | |
| 2049 Fiscal Year | |
| Grounds: Drywell Maintenance | \$6,663.87 |
| Lighting: SolarKing (Controllers & Lights) | \$5,553.22 |
| Paint: Walls, Fencing, Monuments, Ramadas | \$79,966.40 |
| Sub Total | \$92,183.49 |
| | |
| 2051 Fiscal Year | |
| Lighting: SolarKing (Batteries) | \$2,356.57 |
| Sub Total | \$2,356.57 |

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Roofs: Metal, Ramadas (Unfunded)

| | | | |
|-------------------|-----------|-------------------------------|-----------|
| Category | 020 Roofs | Quantity | 1 comment |
| | | Unit Cost | \$0.000 |
| | | % of Replacement | 0.00% |
| | | Current Cost | \$0.00 |
| Placed In Service | 01/08 | Future Cost | \$0.00 |
| Useful Life | n.a. | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | n.a. | Monthly Member Contribution | \$0.00 |
| Replacement Year | n.a. | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$0.00 |

Comments:

We are not budgeting to replace the metal ramada roofs because they have an indefinite useful life and should last for the life of the ramada if properly maintained. Any required repairs should be handled on an as needed basis and the expense paid for out of the annual operating budget.

Paint: Walls, Fencing, Monuments, Ramadas

| | | | |
|-------------------|--------------|-------------------------------|--------------|
| Category | 030 Painting | Quantity | 1 total |
| | | Unit Cost | \$36,000.000 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$36,000.00 |
| Placed In Service | 01/21 | Future Cost | \$42,985.88 |
| Useful Life | 7 | | |
| | | Assigned Reserves at FYB | \$5,142.86 |
| Remaining Life | 6 | Monthly Member Contribution | \$244.86 |
| Replacement Year | 2028 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$244.86 |

Comments:

The common area facing block walls, wrought iron fencing, steel split rail fencing (culvert rails) & monument signs were repainted in early 2021 by EmpireWorks at a cost of \$32,613.11. We are budgeting to repaint these components every seven (7) years, and have also included a provision to repaint the metal ramada support structures (3).

NOTE: Should the client choose to repaint the wrought iron fencing and/or steel split rail fencing on a more frequent basis, we recommend using the accumulated funds to do so. Then, at the time of a future update of this report, we will make an adjustment to this component.

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Fencing: Steel Split Rail (Unfunded)

| | | | |
|-------------------|-------------------|-------------------------------|-----------|
| Category | 040 Fencing/Walls | Quantity | 1 comment |
| | | Unit Cost | \$0.000 |
| | | % of Replacement | 0.00% |
| | | Current Cost | \$0.00 |
| Placed In Service | 01/08 | Future Cost | \$0.00 |
| Useful Life | n.a. | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | n.a. | Monthly Member Contribution | \$0.00 |
| Replacement Year | n.a. | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$0.00 |

Comments:

We are not budgeting to replace the steel split rail fencing because it has an indefinite life. Repairs should be handled on an "as needed" basis using operating funds.

Fencing: Wrought Iron, Replace (100%)

| | | | |
|-------------------|-------------------|-------------------------------|--------------|
| Category | 040 Fencing/Walls | Quantity | 1 total |
| | | Unit Cost | \$34,125.000 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$34,125.00 |
| Placed In Service | 01/14 | Future Cost | \$65,387.03 |
| Useful Life | 30 | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | 22 | Monthly Member Contribution | \$89.62 |
| Replacement Year | 2044 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$89.62 |

Comments:

This component budgets to replace the wrought iron fencing at the following locations that is 100% the responsibility of the Association to maintain:

- east perimeter along 41st Drive across from lots 69 & 81
- east perimeter along 41st Drive across from lots 106 & 114
- NW corner around the Beautiful Lane cul-de-sac (installed in 2018/2018)

| | | | | |
|------------------------|---|---------|---|-------------|
| 975 LF of 5'7" fencing | @ | \$35.00 | = | \$34,125.00 |
| | | TOTAL | = | \$34,125.00 |

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Fencing: Wrought Iron, Replace (50%)

| | | | |
|-------------------|-------------------|-------------------------------|-------------|
| Category | 040 Fencing/Walls | Quantity | 1 total |
| | | Unit Cost | \$35,850.00 |
| | | % of Replacement | 50.00% |
| | | Current Cost | \$17,925.00 |
| Placed In Service | 01/14 | Future Cost | \$34,346.15 |
| Useful Life | 30 | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | 22 | Monthly Member Contribution | \$47.07 |
| Replacement Year | 2044 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$47.07 |

Comments:

This component budgets to replace the wrought iron view fencing located on boundary lines between lots & common area. The cost to replace this fencing is to be shared on a 50% - 50% basis between the Association and the individual lot owners where the fencing is located. Refer to page 13, Section 4.9(d) of the CC&Rs for an explanation of the maintenance responsibilities.

| | | | | |
|--------------------------|---|---------|---|-------------|
| 1,195 LF of 4'6" fencing | @ | \$30.00 | = | \$35,850.00 |
| | | TOTAL | = | \$35,850.00 |

Walls: Block (Repairs)

| | | | |
|-------------------|-------------------|-------------------------------|----------------|
| Category | 040 Fencing/Walls | Quantity | 48,500 sq. ft. |
| | | Unit Cost | \$25.000 |
| | | % of Replacement | 2.00% |
| | | Current Cost | \$24,250.00 |
| Placed In Service | 01/08 | Future Cost | \$38,914.13 |
| Useful Life | 10 | | |
| Adjustment | +20 | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | 16 | Monthly Member Contribution | \$80.80 |
| Replacement Year | 2038 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$80.80 |

Comments:

This component will accumulate funds for 30 years, and then on a continuous 10 year cycle, for the major repair/replacement of a percentage of the common area facing block walls. The accumulate funds should be used as needed, and the percentage budgeted for repair/replacement should be adjusted over time as conditions dictate.

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Lighting: SolarKing (Batteries)

| | | | |
|-------------------|--------------|-------------------------------|------------|
| Category | 050 Lighting | Quantity | 1 total |
| | | Unit Cost | \$1,000.00 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$1,000.00 |
| Placed In Service | 01/19 | Future Cost | \$1,030.00 |
| Useful Life | 4 | | |
| | | Assigned Reserves at FYB | \$750.00 |
| Remaining Life | 1 | Monthly Member Contribution | \$11.72 |
| Replacement Year | 2023 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$11.72 |

Comments:

This component budget \$1,000 every four years to replace the batteries (4) associated with the SolarKing lighting systems at the community ramadas (3) & monument sign (1).

Lighting: SolarKing (Controllers & Lights)

| | | | |
|-------------------|--------------|-------------------------------|------------|
| Category | 050 Lighting | Quantity | 1 total |
| | | Unit Cost | \$2,500.00 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$2,500.00 |
| Placed In Service | 01/19 | Future Cost | \$3,564.40 |
| Useful Life | 15 | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | 12 | Monthly Member Contribution | \$10.51 |
| Replacement Year | 2034 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$10.51 |

Comments:

This component budget \$2,500 every 15 years to replace the controllers (4), light fixtures & cages associated with the SolarKing lighting systems at the community ramadas (3) & monument sign (1).

NOTE: There is one light fixture at each of the three ramadas, and three light fixtures w/cages at the monument sign.

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Tract A: Park Equipment

| | | | |
|-------------------|-----------|-------------------------------|------------|
| Category | 065 Parks | Quantity | 1 total |
| | | Unit Cost | \$4,500.00 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$4,500.00 |
| Placed In Service | 01/14 | Future Cost | \$5,534.43 |
| Useful Life | 15 | | |
| | | Assigned Reserves at FYB | \$2,400.00 |
| Remaining Life | 7 | Monthly Member Contribution | \$17.12 |
| Replacement Year | 2029 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$17.12 |

Comments:

This component will accumulate funds on a 15 year cycle for the replacement of the following park equipment on an "as needed" basis:

- 1 - 6' picnic table (center post)
- 2 - 6' benches (surface mount)
- 1 - trash receptacle
- 1 - charcoal bbq grill (pedestal mounted)

Location: between Lots 27 & 28

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Tract A: Playstructure

| | | | |
|-------------------|-----------|-------------------------------|-------------|
| Category | 065 Parks | Quantity | 1 total |
| | | Unit Cost | \$40,000.00 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$40,000.00 |
| Placed In Service | 01/14 | Future Cost | \$57,030.44 |
| Useful Life | 20 | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | 12 | Monthly Member Contribution | \$168.18 |
| Replacement Year | 2034 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$168.18 |

Comments:

This component budgets to replace the playstructure. The cost includes a provision for sand replenishment on an "as needed" basis.

Location: between Lots 27 & 28

Tract A: Tot Turf

| | | | |
|-------------------|-----------|-------------------------------|-------------|
| Category | 065 Parks | Quantity | 310 sq. ft. |
| | | Unit Cost | \$22.000 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$6,820.00 |
| Placed In Service | 01/14 | Future Cost | \$9,723.69 |
| Useful Life | 20 | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | 12 | Monthly Member Contribution | \$28.68 |
| Replacement Year | 2034 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$28.68 |

Comments:

This component budgets to replace the Tot Turf in conjunction with the replacement of the playstructure. The accumulated funds should be used for repairs and/or FlexCoat applications on an "as needed" basis.

Location: between Lots 27 & 28

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Tract V: Park Equipment

| | | | |
|-------------------|-----------|-------------------------------|------------|
| Category | 065 Parks | Quantity | 1 total |
| | | Unit Cost | \$6,500.00 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$6,500.00 |
| Placed In Service | 01/14 | Future Cost | \$7,994.18 |
| Useful Life | 15 | | |
| | | Assigned Reserves at FYB | \$3,466.67 |
| Remaining Life | 7 | Monthly Member Contribution | \$24.73 |
| Replacement Year | 2029 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$24.73 |

Comments:

This component will accumulate funds on a 15 year cycle for the replacement of the following park equipment on an "as needed" basis:

- 2 - 6' picnic tables (center post)
- 1 - 6' bench (surface mount)
- 2 - trash receptacles
- 2 - charcoal bbq grills (pedestal mounted)

Location: large park area off of 42nd Drive

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Tract V: Playstructure

| | | | |
|-------------------|-----------|-------------------------------|-------------|
| Category | 066 Parks | Quantity | 1 total |
| | | Unit Cost | \$40,000.00 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$40,000.00 |
| Placed In Service | 01/14 | Future Cost | \$57,030.44 |
| Useful Life | 20 | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | 12 | Monthly Member Contribution | \$168.18 |
| Replacement Year | 2034 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$168.18 |

Comments:

This component budgets to replace the playstructure. The cost includes a provision for wood fiber replenishment on an "as needed" basis.

Location: large park area off of 42nd Drive

Tract V: Tot Turf & Sand Removal (2022)

One Time Replacement

| | | | |
|-------------------|-----------|-------------------------------|-------------|
| Category | 066 Parks | Quantity | 1 total |
| | | Unit Cost | \$11,491.62 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$11,491.62 |
| Placed In Service | 01/14 | Future Cost | \$0.00 |
| Useful Life | 8 | | |
| | | Assigned Reserves at FYB | \$11,491.62 |
| Remaining Life | 0 | Monthly Member Contribution | \$0.00 |
| Replacement Year | 2022 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$0.00 |

Comments:

\$11,491.62 was spent in early 2022 to remove the Tot Turf at the playstructure play area, install an ADA ramp, remove the sand & supply/install engineered wood fiber. This is a one time expense in 2022 to account for this project.

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Grounds: Concrete Components (Unfunded)

| | | | |
|-------------------|-------------|-------------------------------|-----------|
| Category | 100 Grounds | Quantity | 1 comment |
| | | Unit Cost | \$0.00 |
| | | % of Replacement | 0.00% |
| | | Current Cost | \$0.00 |
| Placed In Service | 01/08 | Future Cost | \$0.00 |
| Useful Life | n.a. | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | n.a. | Monthly Member Contribution | \$0.00 |
| Replacement Year | n.a. | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$0.00 |

Comments:

We are not budgeting for repair or replacement of concrete components in this analysis. It is anticipated that any repairs/replacements required will be addressed immediately due to safety concerns. There should not be a need for complete replacement at a single point in time, and good maintenance practice won't allow the need for repairs to accumulate to a point of major expense. We recommend that a line item be set up in the annual operating budget to account for potential concrete repairs/replacements on an "as needed" basis. However, should the client wish to include budgeting for concrete components as a reserve expense, we will do so at their request (cost and useful life to be provided by client).

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

| |
|-------------------------------------|
| Grounds: Drywell Maintenance |
|-------------------------------------|

| | | | |
|-------------------|-------------|-------------------------------|------------|
| Category | 100 Grounds | Quantity | 1 total |
| | | Unit Cost | \$3,000.00 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$3,000.00 |
| Placed In Service | 01/08 | Future Cost | \$3,278.18 |
| Useful Life | 3 | | |
| | | Assigned Reserves at FYB | \$3,000.00 |
| Remaining Life | 0 | Monthly Member Contribution | \$44.39 |
| Replacement Year | 2022 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$44.39 |

Comments:

There are seven (7) drywells in the community water retention tracts. Since there is no provision in the client's operating budget for drywell maintenance (repairs & hydrovactor cleaning), this component includes a provision for such. The accumulated funds should be used on an "as needed" basis for drywell maintenance. The following comments apply:

Drywell systems should be inspected annually to determine how much debris has accumulated in the system and to develop a clean out schedule. Some drywell systems will require immediate repair of broken components and clean out, while others won't require maintenance for a number of years. On average, drywell systems require clean out every 5 - 7 years. A drywell should be cleaned out once 10% or more of the chamber is occupied. If maintained properly, drywells are designed to last as long as any other part of the community infrastructure. Thus, no provision has been included for their replacement.

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Grounds: Granite Replenishment

| | | | |
|-------------------|-------------|-------------------------------|--------------|
| Category | 100 Grounds | Quantity | 1,750 tons |
| | | Unit Cost | \$75.000 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$131,250.00 |
| Placed In Service | 01/14 | Future Cost | \$161,420.94 |
| Useful Life | 15 | | |
| | | Assigned Reserves at FYB | \$49,619.84 |
| Remaining Life | 7 | Monthly Member Contribution | \$610.66 |
| Replacement Year | 2029 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$610.66 |

Comments:

We estimated that there is approximately 350,000 sq. ft. of common area granite. We are budgeting to replenish the granite with a 1" layer added to the existing base every 15 years. The cost is an estimate for purchase, delivery and spreading.

NOTE: Should the client choose not to replenish all of the granite at a single point in time, the accumulated funds can be used to replenish on an "as needed" basis.

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Grounds: Irrigation Controllers

| | | | |
|-------------------|-------------|-------------------------------|-------------|
| Category | 100 Grounds | Quantity | 1 total |
| | | Unit Cost | \$5,000.000 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$5,000.00 |
| Placed In Service | 01/20 | Future Cost | \$6,719.58 |
| Useful Life | 12 | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | 10 | Monthly Member Contribution | \$24.53 |
| Replacement Year | 2032 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$24.53 |

Comments:

There are 10 irrigation controllers scattered throughout the community. All but one of them has been replaced within the last three years (no information was provided by the client). This component will accumulate funds on a 12 year cycle for the replacement of the irrigation controllers on an "as needed" basis. The inventory includes:

- 1 - Leit solar controller
- 8 - Hunter XC Hybrid controllers
- 1 - Hunter ICC2 controller

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Grounds: Irrigation System (Unfunded)

| | | | |
|-------------------|-------------|-------------------------------|-----------|
| Category | 100 Grounds | Quantity | 1 comment |
| | | Unit Cost | \$0.00 |
| | | % of Replacement | 0.00% |
| | | Current Cost | \$0.00 |
| Placed In Service | 01/14 | Future Cost | \$0.00 |
| Useful Life | n.a. | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | n.a. | Monthly Member Contribution | \$0.00 |
| Replacement Year | n.a. | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$0.00 |

Comments:

Irrigation systems are one of the most difficult items to budget for without specific information provided by an expert who is familiar with the system inventory and system condition. We have been advised by irrigation system experts that most system components (piping, sprinkler heads, valves, etc) have a useful life of 20+ years. However, budgeting for the replacement of an irrigation system requires evaluation of the present condition (to identify remaining useful life) and replacement cost - both of which call for expert evaluation, but fall outside the scope of a reserve study.

Therefore, we recommend that the Association board and/or management company have the system evaluated to determine the appropriate scope of work, projected replacement cost and remaining life, all of which are necessary so that budgeting can be included in a revision or future update of this analysis.

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Grounds: Mailboxes (Pedestal Sets)

| | | | |
|-------------------|-------------|-------------------------------|-------------|
| Category | 100 Grounds | Quantity | 1 total |
| | | Unit Cost | \$24,800.00 |
| | | % of Replacement | 100.00% |
| | | Current Cost | \$24,800.00 |
| Placed In Service | 01/08 | Future Cost | \$29,612.50 |
| Useful Life | 20 | | |
| | | Assigned Reserves at FYB | \$17,360.00 |
| Remaining Life | 6 | Monthly Member Contribution | \$79.28 |
| Replacement Year | 2028 | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$79.28 |

Comments:

| | | | | | |
|--|----------------------------------|---|------------|---|-------------|
| | 2 8 box sets w/ 2 parcel lockers | @ | \$1,700.00 | = | \$3,400.00 |
| | 4 12 box sets w/1 parcel locker | @ | \$1,750.00 | = | \$7,000.00 |
| | 8 16 box sets w/2 parcel lockers | @ | \$1,800.00 | = | \$14,400.00 |
| | | | TOTAL | = | \$24,800.00 |

Grounds: Monument Sign Letters (Unfunded)

| | | | |
|-------------------|-------------|-------------------------------|-----------|
| Category | 100 Grounds | Quantity | 1 comment |
| | | Unit Cost | \$0.00 |
| | | % of Replacement | 0.00% |
| | | Current Cost | \$0.00 |
| Placed In Service | 01/08 | Future Cost | \$0.00 |
| Useful Life | n.a. | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | n.a. | Monthly Member Contribution | \$0.00 |
| Replacement Year | n.a. | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$0.00 |

Comments:

We are not budgeting to replace the solid steel letters making up the monument sign that indicates "ARTESA" because they have an indefinite useful life and should last for the life of the community. Any required repairs and/or replacements should be handled as needed using funds from the operating budget. Should the client wish to budget to replace these letters for aesthetic/remodeling purposes, we will do so at upon request in a revision or future update of this report.

Artesa

Component Detail

Directed Cashflow Calculation Method; Sorted by Category

Grounds: Tree Trimming (Unfunded)

| | | | |
|-------------------|-------------|-------------------------------|-----------|
| Category | 100 Grounds | Quantity | 1 comment |
| | | Unit Cost | \$0.00 |
| | | % of Replacement | 0.00% |
| | | Current Cost | \$0.00 |
| Placed In Service | 01/08 | Future Cost | \$0.00 |
| Useful Life | n.a. | | |
| | | Assigned Reserves at FYB | \$0.00 |
| Remaining Life | n.a. | Monthly Member Contribution | \$0.00 |
| Replacement Year | n.a. | Monthly Interest Contribution | \$0.00 |
| | | Total Monthly Contribution | \$0.00 |

Comments:

Tree trimming is accounted for as an annual operating expense.

Artesa

Detail Report Index

| | Page |
|--|-------------|
| Fencing: Steel Split Rail (Unfunded) | 12 |
| Fencing: Wrought Iron, Replace (100%) | 12 |
| Fencing: Wrought Iron, Replace (50%) | 13 |
| Grounds: Concrete Components (Unfunded) | 19 |
| Grounds: Drywell Maintenance | 20 |
| Grounds: Granite Replenishment | 21 |
| Grounds: Irrigation Controllers | 22 |
| Grounds: Irrigation System (Unfunded) | 23 |
| Grounds: Mailboxes (Pedestal Sets) | 24 |
| Grounds: Monument Sign Letters (Unfunded) | 24 |
| Grounds: Tree Trimming (Unfunded) | 25 |
| Lighting: SolarKing (Batteries) | 14 |
| Lighting: SolarKing (Controllers & Lights) | 14 |
| Paint: Walls, Fencing, Monuments, Ramadas | 11 |
| Roofs: Metal, Ramadas (Unfunded) | 11 |
| Tract A: Park Equipment | 15 |
| Tract A: Playstructure | 16 |
| Tract A: Tot Turf | 16 |
| Tract V: Park Equipment | 17 |
| Tract V: Playstructure | 18 |
| Tract V: Tot Turf & Sand Removal (2022) | 18 |
| Walls: Block (Repairs) | 13 |

Number of components included in this reserve analysis is 22.